

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

# OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-02782
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator  
YATES PETROLEUM CORPORATION

3. Address of Operator  
105 South 4th St., Artesia, NM 88210

4. Well Location Bottom Hole Location: 1650' FNL & 1980' FWL of Section 11-T16S-R35E

Face: Unit Letter F : 1980 Feet From The North Line and 1980 Feet From The West Line

Section 11 Township 16S Range 35E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3982' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

## SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: Spud on re-entry ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-8-97 - Cleaned out cellar. Removed dry hole marker. Found 8-5/8" casing stub. Welded on 11" X 5K slip on head.  
8-9-18-97 - Building location.  
8-19-27-97 - Waiting on re-entry equipment.  
8-28-97 - Moving in equipment for re-entry.  
8-29-97 - Moved in re-entry equipment. Moved in and rigged up pulling unit. Nippled up spool and 11" X 3000 BOP. NOTE: Notified Bonnie w/OCD of plans to spud.  
8-30-97 - TIH with swivel, drill collars and mill tooth bit. Spudded at 8:45 PM 8-29-97. Drilled out surface plug and fell out at 15'. Picked up rest of drill collars & 2-7/8" tubing. TIH to 4100'. Circulate 45 minutes. Washed down to shoe plug at 4655'. Circulate clean with 9# brine. Test casing and BOP to 1000 psi for 5 minutes. Shut in.  
8-31-9-2-97 - Shut in.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Operations Technician DATE Sept. 3, 1997  
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use) ORIGINAL SIGNED BY CHRIS WILLIAMS  
DISTRICT I SUPERVISOR

SEP 11 1997

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: