to Appropriate District Office	E. ,y, Minerals and Natural Reso	co surces Department	Form Ci103 Revised 1-1-89
DISTRICT 1 P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION	DIVISION	WELL API NO.
DISTRICT	P.O. Box 2088 Santa Fe, New Mexico 87	7504-2088	30-025-02785
P.O. Drawer DD, Artesia, NM 88210		2000	5. Indicate Type of Lease STATE FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		6. State Oil & Gas Lease No.	
SUNDRY NOT	ICES AND REPORTS ON WELLS	5	
DIFFERENT RESE (FORM (OPOSALS TO DRILL OR TO DEEPEN OF RVOIR. USE "APPLICATION FOR PERM -101) FOR SUCH PROPOSALS.)	TPLUG BACK TO A	7. Lease Name or Unit Agreement Name
1. Type of Well: Off. WELL WELL X	OTTER	·	Prove 1 4 GP
2 Name of Operator YATES PETROLEUM CORPOR			Runnels ASP 8. Well No.
3. Address of Operator			9. Pool name or Wildcat
105 South 4th St., Art 4. Well Location	esia, NM 88210		Townsend Morrow
	0 North		
Unit Letter::	0 Feet From The North	Line and) Feet From The East
Section 1.1	Township 1.6S Range	35E r	MPM Lea Cour
	10. Elevation (Show whether DF,	RKB, RT, GR, etc.)	MEM Lea Coun
	Unknow		
	Appropriate Box to Indicate National Appropriate Box to Indicate Nation		
NOTICE OF IN	ENTION TO:	SUB	SEQUENT REPORT OF:
	PLUG AND ABANDON	EMEDIAL WORK	
		OMMENCE DRILLING	
PULL OR ALTER CASING			
		ASING TEST AND CEI	
DTHER:		T-1 100 00	
12. Describe Proposed or Completed Opera work) SEE RULE 1103	ions (Clearly state all pertinent details, and gi		ing estimated date of starting any proposed
5-21-98 - TIH with 4-3 tubing open ended to 3 2% CaCl2. TOOH with t off. Installed regula	ions (Clearly state all pertinent details, and gi /4" drill collars. , TOOH 78'. Loaded hole. Mixe ubing, Nippled down BOP	and laid down and laid down d and pumped 1 . Filled 8-5, PLUGGED AND	ing estimated date of starting any proposed n collars. TIH with 2-7/8" 100 sacks Class C cement wit /8" casing with cement. Cut ABANDONED - FINAL PEDODT
5-21-98 - TIH with 4-3 tubing open ended to 3 2% CaCl2. TOOH with t off. Installed regula	ions (Clearly state all pertinent details, and gi /4" drill collars. , TOOH 78'. Loaded hole. Mixe ubing. Nippled down BOP tion abandonment marker.	and laid down and laid down d and pumped 1 . Filled 8-5, PLUGGED AND	ing estimated date of starting any proposed n collars. TIH with 2-7/8" 100 sacks Class C cement wit /8" casing with cement. Cut ABANDONED - FINAL PEDODT
5-21-98 - TIH with 4-3 tubing open ended to 3 2% CaCl2. TOOH with t off. Installed regula	ions (Clearly state all pertinent details, and gi /4" drill collars. , TOOH 78'. Loaded hole. Mixe ubing. Nippled down BOP tion abandonment marker.	and laid down and laid down d and pumped 1 . Filled 8-5, PLUGGED AND	ing estimated date of starting any proposed n collars. TIH with 2-7/8" 100 sacks Class C cement wit /8" casing with cement. Cut ABANDONED - FINAL PEDODT
5-21-98 - TIH with 4-3 tubing open ended to 3 2% CaCl2. TOOH with t off. Installed regula	ions (Clearly state all pertinent details, and gi /4" drill collars. , TOOH 78'. Loaded hole. Mixe ubing. Nippled down BOP tion abandonment marker.	and laid down and laid down d and pumped 1 . Filled 8-5, PLUGGED AND	ing estimated date of starting any proposed n collars. TIH with 2-7/8" 100 sacks Class C cement wit /8" casing with cement. Cut ABANDONED - FINAL PEDODT
5-21-98 - TIH with 4-3 tubing open ended to 3 2% CaCl2. TOOH with t off. Installed regula	ions (Clearly state all pertinent details, and gi /4" drill collars. , TOOH 78'. Loaded hole. Mixe ubing. Nippled down BOP tion abandonment marker.	and laid down and laid down d and pumped 1 . Filled 8-5, PLUGGED AND	ing estimated date of starting any proposed n collars. TIH with 2-7/8" 100 sacks Class C cement wit /8" casing with cement. Cut ABANDONED - FINAL PEDODT
5-21-98 - TIH with 4-3 tubing open ended to 3 2% CaCl2. TOOH with t off. Installed regula	ions (Clearly state all pertinent details, and gi /4" drill collars. , TOOH 78'. Loaded hole. Mixe ubing. Nippled down BOP tion abandonment marker.	and laid down and laid down d and pumped 1 . Filled 8-5, PLUGGED AND	ing estimated date of starting any proposed n collars. TIH with 2-7/8" 100 sacks Class C cement wit /8" casing with cement. Cut ABANDONED - FINAL PEDODT
5-21-98 - TIH with 4-3 tubing open ended to 3 2% CaCl2. TOOH with t off. Installed regula Plugging completed 5-2	ions (Clearly state all pertinent details, and gi /4" drill collars. , TOOH 78'. Loaded hole. Mixe ubing. Nippled down BOP tion abandonment marker. 0-98. NOTE: Plugging w	and laid down and laid down d and pumped . . Filled 8-5, <u>PLUGGED AND</u> itnessed by Ja	ing estimated date of starting any proposed n collars. TIH with 2-7/8" 100 sacks Class C cement wit /8" casing with cement. Cut ABANDONED - FINAL PEDODT
5-21-98 - TIH with 4-3 tubing open ended to 3 2% CaCl2. TOOH with t off. Installed regula Plugging completed 5-2	ions (Clearly state all pertinent details, and gi /4" drill collars. , TOOH 78'. Loaded hole. Mixe ubing. Nippled down BOP tion abandonment marker.	and laid down and laid down d and pumped . . Filled 8-5, <u>PLUGGED AND</u> itnessed by Ja	ing estimated date of starting any proposed n collars. TIH with 2-7/8" 100 sacks Class C cement wit /8" casing with cement. Cut ABANDONED - FINAL PEDODT
5-21-98 - TIH with 4-3 tubing open ended to 3 2% CaCl2. TOOH with t off. Installed regula Plugging completed 5-2	ions (Clearly state all pertinent details, and gi /4" drill collars. , TOOH 78'. Loaded hole. Mixe ubing. Nippled down BOP tion abandonment marker. 0-98. NOTE: Plugging w	and laid down and laid down d and pumped . . Filled 8-5, <u>PLUGGED AND</u> itnessed by Ja	ing estimated date of starting any proposed n collars. TIH with 2-7/8" 100 sacks Class C cement wit /8" casing with cement. Cut ABANDONED - FINAL REPORT. ack Griffin w/OCD-Hobbs.
5-21-98 - TIH with 4-3 tubing open ended to 3 2% CaCl2. TOOH with t off. Installed regula Plugging completed 5-2 I hereby certify that the information above is gree SKONATURE	ions (Clearly state all pertinent details, and gi /4" drill collars. , TOOH 78'. Loaded hole. Mixe ubing. Nippled down BOP tion abandonment marker. 0-98. NOTE: Plugging w	and laid down and laid down d and pumped 1 . Filled 8-5, <u>PLUGGED AND</u> itnessed by Ja	n collars. TIH with 2-7/8" 100 sacks Class C cement wit /8" casing with cement. Cut ABANDONED - FINAL REPORT. ack Griffin w/OCD-Hobbs.
5-21-98 - TIH with 4-3 tubing open ended to 3 2% CaCl2. TOOH with t off. Installed regula Plugging completed 5-2 Ihereby certify that the information above is pro-	ions (Clearly state all pertinent details, and gi /4" drill collars. , TOOH 78'. Loaded hole. Mixe ubing. Nippled down BOP tion abandonment marker. 0-98. NOTE: Plugging w	and laid down and laid down d and pumped 1 . Filled 8-5, <u>PLUGGED AND</u> itnessed by Ja	ing estimated date of starting any proposed n collars. TIH with 2-7/8" 100 sacks Class C cement wit /8" casing with cement. Cut ABANDONED - FINAL REPORT. ack Griffin w/OCD-Hobbs.
5-21-98 - TIH with 4-3 tubing open ended to 3 2% CaCl2. TOOH with t off. Installed regula Plugging completed 5-2 I hereby certify that the information above is gree SKONATURE	ions (Clearly state all pertinent details, and gi /4" drill collars. , TOOH 78'. Loaded hole. Mixe ubing. Nippled down BOP tion abandonment marker. 0-98. NOTE: Plugging w	and laid down and laid down d and pumped 1 . Filled 8-5, <u>PLUGGED AND</u> itnessed by Ja	n collars. TIH with 2-7/8" 100 sacks Class C cement wit /8" casing with cement. Cut ABANDONED - FINAL REPORT. ack Griffin w/OCD-Hobbs.
5-21-98 - TIH with 4-3 tubing open ended to 3 2% CaCl2. TOOH with t off. Installed regula Plugging completed 5-2 I hereby certify that the information above is pre- skinkature TYTE OR FRINT NAME Rusty Klein (This space for State Use)	ions (Clearly state all pertinent details, and gi /4" drill collars. , TOOH 78'. Loaded hole. Mixe ubing. Nippled down BOP tion abandonment marker. 0-98. NOTE: Plugging w	and laid down and laid down d and pumped 1 . Filled 8-5, <u>PLUGGED AND</u> itnessed by Ja	n collars. TIH with 2-7/8" 100 sacks Class C cement wit /8" casing with cement. Cut ABANDONED - FINAL REPORT. ack Griffin w/OCD-Hobbs.
5-21-98 - TIH with 4-3 tubing open ended to 3 2% CaCl2. TOOH with to off. Installed regula Plugging completed 5-2 Hugging completed 5-2 I hereby certify that the information above is great SKONATURE TYPE OR FRENT NAME Rusty Klein (This space for State Use)	ions (Clearly state all pertinent details, and gi /4" drill collars. , TOOH 78'. Loaded hole. Mixe ubing. Nippled down BOP tion abandonment marker. 0-98. NOTE: Plugging w	and laid down and laid down d and pumped 1 . Filled 8-5, <u>PLUGGED AND</u> itnessed by Ja	n collars. TIH with 2-7/8" 100 sacks Class C cement wit /8" casing with cement. Cut ABANDONED - FINAL REPORT. ack Griffin w/OCD-Hobbs.
5-21-98 - TIH with 4-3 tubing open ended to 3 2% CaCl2. TOOH with t off. Installed regula Plugging completed 5-2 I hereby certify that the information above is pre- skinkature TYTE OR FRINT NAME Rusty Klein (This space for State Use)	ions (Clearly state all pertinent details, and gi /4" drill collars. ,TOOH 78'. Loaded hole. Mixe ubing. Nippled down BOP tion abandonment marker. 0-98. NOTE: Plugging w and complete to the best of my knowledge and belief. ITTLE	and laid down and laid down d and pumped 1 . Filled 8-5, <u>PLUGGED AND</u> itnessed by Ja	chnician chnich
5-21-98 - TIH with 4-3 tubing open ended to 3 2% CaCl2. TOOH with to off. Installed regula Plugging completed 5-2 Hereby certify the the information above is gree SKONATURE TYPE OR FRINT NAME Rusty Klein (This space for State Use)	ions (Clearly state all pertinent details, and gi /4" drill collars. ,TOOH 78'. Loaded hole. Mixe ubing. Nippled down BOP tion abandonment marker. 0-98. NOTE: Plugging w and complete to the best of my knowledge and belief. ITTLE	and laid down and laid down d and pumped 1 . Filled 8-5, <u>PLUGGED AND</u> itnessed by Ja	chnician chnich
5-21-98 - TIH with 4-3 tubing open ended to 3 2% CaCl2. TOOH with to off. Installed regula Plugging completed 5-2 Hereby certify that the information above is gree SKONATURE TYPE OR FRINT NAME Rusty Klein (This space for Size Use)	ions (Clearly state all pertinent details, and gi /4" drill collars. ,TOOH 78'. Loaded hole. Mixe ubing. Nippled down BOP tion abandonment marker. 0-98. NOTE: Plugging w and complete to the best of my knowledge and belief. ITTLE	and laid down and laid down d and pumped 1 . Filled 8-5, <u>PLUGGED AND</u> itnessed by Ja	chnician chnich