ATTACHMENT for form C-1 B-H State, Lea County, NM.

5/6 Swabbing back frac residue, getting a little gas that will burn, no oil yet.

_ `

- 5/8 TP 200#, FL 3800' from surface, continuing to swab.
- 5/12 Running btm hole pressure test, well had no pressure this AM. Prep to perf.
- 5/13 Perfd 8745, 73, 75, 78, 89, 92, 8801 & 03, btm hole pressure 2371#, FL approx 3500', acidized w/3000 gals DS-30 acid & 8 ball sealers.
- 5/14 TP 300#, FL 2000', can't swab down, getting a little gas & lots of water, prep to P&A.

, · · ·

Stelling and the set