

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State ☒ Fee ☐
5. State Oil & Gas Lease No. 45981

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER- DEPLETED	7. Unit Agreement Name
2. Name of Operator PAN AMERICAN PETROLEUM CORPORATION	8. Farm or Lease Name STATE AL
3. Address of Operator BOX 68, HOBBS, N. M. 88240	9. Well No. 1
4. Location of Well UNIT LETTER D 330 FEET FROM THE NORTH LINE AND 330 FEET FROM THE WEST LINE, SECTION 12 TOWNSHIP 16-S RANGE 35-E NMPM. TOWNSEND WOLF CAMP	10. Field and Pool, or Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3991' R. D. B.	12. County LEA

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pursuant to verbal authority to P&A rec'd 3-16-70,
Mr. L. Clements to A.M. Landi. abandonment to be as
follows:
Spot 5004. cmt plug - PBD 10,500 to 10,250 (PERFS: 10,455-10295).
Pull 5 1/2" Csg from free point. (Cmt TCMT @ 9000') & Spot 25 sx in + Out of stub.
SPOT 25x, 50' above & below Tabo @ 8150 (Do NOT SET IF NOT EXPOSED)
SPOT 26x, 6348-6248 (T-GUOR-6298), IF EXPOSED, 50 SX in & Out of 8 7/8" CSA 4700'.
Pull 8 7/8" Csg from free point. (Cmt TCMT 1500') & Spot 25 sx in + Out of stub.
SPOT 25 sx in + Out at Top Set @ 1890'.
" 50 sx " " 13 7/8" CSA 360'
" 10 sx @ surface & erect P&A marker.
make final cleanup & restore ground to contour.
13 7/8" CSA 360 - circ
8 7/8" CSA 4700 - TCMT 1500'
5 1/2" CSA 10720 - " 9000'
PBD - 10,500'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED _____	TITLE AREA SUPERINTENDENT	DATE MAR 18 1970
APPROVED BY 042- NMOC- H 1- SUSP 1- ACJR 1- RRY	TITLE _____	DATE 1970

