

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 no Brazos Rd, Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. <b>30-025-02796</b>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Eidson "A" WN
8. Well No. 3
9. Pool name or Wildcat Shoe Bar (Wolfcamp)

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other
2. Name of Operator DEVON ENERGY CORPORATION (NEVADA)
3. Address of Operator 20 NORTH BROADWAY, SUITE 1500, OKLAHOMA CITY, OKLAHOMA 73102 (405) 236-3611

4 Well Location Unit Letter L: 1980 Feet From The South Line and 990 Feet From The West Section 26 Township 16S Range 35E NMPM Lea County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3967' GR
--	--

Check Appropriate Box To Indicate Nature Of Notice, Report, Or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103.

Propose to P & A on approx. 8/1/95 as follows: Set CIBP @ 10,100' w/ 35' cmt on top. Spot 25sx cmt plug over the Tubbs @ 7487'. Pull parted 5 1/2" csg @ 4500'. Spot 100' cmt plug over csg stub @ 4500'. Spot 25 sx cmt plug over the top of the salt @ 1977'. Spot 10 sx surf plug. Cut off wellhead & install dryhole marker.

NOTE: P & A procedure was discussed w/ Gary Wink of the NMOCD on 7/11/95.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE E. L. Buttross Jr. TITLE District Engineer DATE July 12, 1995  
TYPE OR PRINT NAME Ernie Buttross TELEPHONE NO. (405) 235-3611

This space for State use)

ORIGINAL SIGNED BY GARY WINK TITLE FIELD REP. II DATE JUL 19 1995  
Approved by \_\_\_\_\_  
Conditions of approval, if any: \_\_\_\_\_

Not to be used  
mp

2001 21 100

**RECEIVED**

JUL 18 1995  
JCD HOBBS  
OFFICE