to Appropriate District Office	State of New Energy, oreals and Natural	Resources Department	Form C-103 Revised 1-1-89
DISTRICT I	OIL CONSERVAT	ION DIVISION	WELL API NO.
P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2		30-025-02801
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexic	co 87504-2088	5. Indicate Type of Lease STATE XX FEE
DISTRICT III 1000 Rio Brazos Rd., Azzec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS		6. State Oil & Gas Lease No. VA-698	
(FORM C	OPOSALS TO DRILL OR TO DEEP RVOIR. USE "APPLICATION FOR C-101) FOR SUCH PROPOSALS.)	EN OR PLUG BACK TO A PERMIT	7. Lease Name or Unit Agreement Name
1. Type of Well: OIL OAS WELL X	OTHER		Buffalo ARU State Com
2. Name of Operator			8. Well No.
YATES PETROLEUM CORPOR	RATION	······································	1
3. Address of Operator 105 South 4th St., Art	tesia. NM 88210		9. Pool name or Wildcat Townsend Morrow
4. Well Location			Townsend norrow
Unit Letter <u>K</u> : <u>19</u>	Township 16S	Range 35E her DF, RKB, RT, GR, eic.)	Feet From The West Lin NMPM Lea County
		vailable	
11. Check NOTICE OF IN	Appropriate Box to Indicat TENTION TO:		eport, or Other Data BSEQUENT REPORT OF:
		REMEDIAL WORK	
	CHANGE PLANS		
	CHANGE FLANS	- 1	
PULL OR ALTER CASING			1
		CASING TEST AND C	,
DTHER:] OTHER: Perfor	ate & frac
DTHER: 12 Describe Proposed or Completed Oper work) SEE RULE 1103. 10-15-97 - Moved in a PBTD at 13261'. Pick Flushed with 76 bbls. with logging tools ar 10-16-97 - TIH with H TTIH with 1-11/16" Ga BOP. Set packer. Ni 3000 psi. Rigged up Guns fired - perforat Nippled down treesave 10-17-97 - Flowed dow TIH with packer, on/o 10-18-97 - Finished T	rations (Clearly state all pertinent details and rigged up pulling cled tubing with 500 g . Reversed out 100 bl nd ran GR/CBL log. To lalliburton TCP power amma Ray tool for corn ippled up 7-1/16" X 50 treesaver. Tested N2 ted 12895-12950' w/124 er. Flowed to pit for yn. Swabbed. Loaded off tool and 40 stands CIH with tubing. Nipp ompression. Flanged) OTHER: Perfor a, and give pertinent dates, inclu- unit. TIH with gallons 15% doubl ols. TOOH with t DOH with logging perf system to p relation. TOOH. DOO tree. Flange 2 lines. Pressur 4 .45" holes (6 S r 3 hours. Shut tubing. Release s tubing. Shut w pled down BOP and up wellhead. Swa	ate & frac ding estimated date of starting any proposed bit, scraper and tubing. Tagg e inhibited iron control HCL a ubing. Rigged up wireline. T tools and rigged down wireline erforate. Rigged up wireline. Spaced out tubing. Nippled d d up. Tested annulus popoff t red tubing to 8000 psi with N2. PF - Morrow). Bled pressure of well in. d packer. TOOH with TCP system yell in. I nippled up tree. Set packer bbed tubing dry. Flow testing CONTINUED ON NEXT PAGE: Technician NOV. 4, 1997
DTHER: 12 Describe Proposed or Completed Oper work) SEE RULE 1103. 10-15-97 - Moved in a PBTD at 13261'. Pick Flushed with 76 bbls. with logging tools ar 10-16-97 - TIH with H TTIH with 1-11/16" Ga BOP. Set packer. Ni 3000 psi. Rigged up Guns fired - perforat Nippled down treesave 10-17-97 - Flowed dow TIH with packer, on/o 10-18-97 - Finished T 12830' with 20000# co	rations (Clearly state all pertinent details and rigged up pulling cled tubing with 500 g . Reversed out 100 bl nd ran GR/CBL log. To Halliburton TCP power amma Ray tool for corre ippled up 7-1/16" X 50 treesaver. Tested N2 ted 12895-12950' w/124 er. Flowed to pit for wn. Swabbed. Loaded off tool and 40 stands off tool and 40 stands TH with tubing. Nipp ompression. Flanged to we and complete to the best of my knowledge	OTHER: Perfor and give periment dates, inclu- unit. TIH with gallons 15% doubl ols. TOOH with t DOH with logging perf system to p relation. TOOH. DOO tree. Flange 2 lines. Pressur 4 .45" holes (6 S r 3 hours. Shut tubing. Release s tubing. Shut w pled down BOP and up wellhead. Swa	ate & frac ding estimated date of starting any proposed bit, scraper and tubing. Tagg e inhibited iron control HCL a ubing. Rigged up wireline. T tools and rigged down wireline erforate. Rigged up wireline. Spaced out tubing. Nippled d d up. Tested annulus popoff t red tubing to 8000 psi with N2. PF - Morrow). Bled pressure of well in. d packer. TOOH with TCP system rel in. I nippled up tree. Set packer bbed tubing dry. Flow testing CONTINUED ON NEXT PAGE:
DTHER: 12. Describe Proposed or Completed Oper work) SEE RULE 1103. 10-15-97 - Moved in a PBTD at 13261'. Pick Flushed with 76 bbls. with logging tools ar 10-16-97 - TIH with H TTIH with 1-11/16" Ga BOP. Set packer. Ni 3000 psi. Rigged up Guns fired - perforat Nippled down treesave 10-17-97 - Flowed dow TIH with packer, on/o 10-18-97 - Finished T 12830' with 20000# co 1 hereby certify that the information above is tr SKONATURE TYPE OR PRINT NAME Rusty Klei	rations (Clearly state all pertinent details and rigged up pulling cled tubing with 500 g . Reversed out 100 bl nd ran GR/CBL log. To lalliburton TCP power amma Ray tool for corr ippled up 7-1/16" X 50 treesaver. Tested N2 ted 12895-12950' w/124 er. Flowed to pit for wn. Swabbed. Loaded off tool and 40 stands TH with tubing. Nipp ompression. Flanged to we and complete to the best of my knowledge when the standard of the standard of the standard of the standard of the standard the standard of the best of my knowledge when the standard of the standard of the standard of the standard the standard of the best of my knowledge when the standard of the	OTHER: Perfor and give periment dates, inclu- unit. TIH with gallons 15% doubl ols. TOOH with t DOH with logging perf system to p relation. TOOH. DOO tree. Flange 2 lines. Pressur 4 .45" holes (6 S r 3 hours. Shut tubing. Release s tubing. Shut w pled down BOP and up wellhead. Swa	ate & frac ding estimated date of starting any proposed bit, scraper and tubing. Tagg e inhibited iron control HCL a ubing. Rigged up wireline. T tools and rigged down wireline erforate. Rigged up wireline. Spaced out tubing. Nippled d d up. Tested annulus popoff t red tubing to 8000 psi with N2. PF - Morrow). Bled pressure of well in. d packer. TOOH with TCP system yell in. I nippled up tree. Set packer bbed tubing dry. Flow testing CONTINUED ON NEXT PAGE: Technician NOV. 4, 1997
DTHER: 12. Describe Proposed or Completed Oper work) SEE RULE 1103. 10-15-97 - Moved in a PBTD at 13261'. Pick Flushed with 76 bbls. with logging tools ar 10-16-97 - TIH with H TTIH with 1-11/16" Ga BOP. Set packer. Ni 3000 psi. Rigged up Guns fired - perforat Nippled down treesave 10-17-97 - Flowed dow TIH with packer, on/o 10-18-97 - Finished T 12830' with 20000# co 1hereby certify that the information above is tr SKONATURE	rations (Clearly state all pertinent details and rigged up pulling thed tubing with 500 g . Reversed out 100 bl and ran GR/CBL log. To lalliburton TCP power amma Ray tool for correct ippled up 7-1/16" X 50 treesaver. Tested N2 ted 12895-12950' w/124 er. Flowed to pit for wn. Swabbed. Loaded off tool and 40 stands TH with tubing. Nipp ompression. Flanged to we and complete to the best of my knowledge	OTHER: Perfor and give periment dates, inclu- unit. TIH with gallons 15% doubl ols. TOOH with t DOH with logging perf system to p relation. TOOH. DOO tree. Flange 2 lines. Pressur 4 .45" holes (6 S r 3 hours. Shut tubing. Release s tubing. Shut w pled down BOP and up wellhead. Swa	ate & frac ding estimated date of starting any proposed bit, scraper and tubing. Tagg e inhibited iron control HCL a ubing. Rigged up wireline. T tools and rigged down wireline erforate. Rigged up wireline. Spaced out tubing. Nippled d d up. Tested annulus popoff t red tubing to 8000 psi with N2. PF - Morrow). Bled pressure of well in. d packer. TOOH with TCP system yell in. I nippled up tree. Set packer bbed tubing dry. Flow testing CONTINUED ON NEXT PAGE: Technician NOV. 4, 1997
DTHER: 12. Describe Proposed or Completed Oper work) SEE RULE 1103. 10-15-97 - Moved in a PBTD at 13261'. Pick Flushed with 76 bbls. with logging tools ar 10-16-97 - TIH with H TTIH with 1-11/16" Ga BOP. Set packer. Ni 3000 psi. Rigged up Guns fired - perforat Nippled down treesave 10-17-97 - Flowed dow TIH with packer, on/o 10-18-97 - Finished T 12830' with 20000# co 1 hereby certify that the information above is tr SKONATURE TYPE OR PRINT NAME Rusty Klei	rations (Clearly state all pertinent details and rigged up pulling cled tubing with 500 g . Reversed out 100 bl nd ran GR/CBL log. To lalliburton TCP power amma Ray tool for corr ippled up 7-1/16" X 50 treesaver. Tested N2 ted 12895-12950' w/124 er. Flowed to pit for wn. Swabbed. Loaded off tool and 40 stands TH with tubing. Nipp ompression. Flanged to we and complete to the best of my knowledge when the standard of the standard of the standard of the standard of the standard the standard of the best of my knowledge when the standard of the standard of the standard of the standard the standard of the best of my knowledge when the standard of the) OTHER: Perfor a, and give periment dates, inclu- unit. TIH with gallons 15% doubl ols. TOOH with t DOH with logging perf system to p relation. TOOH. DOO tree. Flange 2 lines. Pressur 4 .45" holes (6 S r 3 hours. Shut tubing. Release s tubing. Shut w pled down BOP and up wellhead. Swa mdbedief.	ate & frac ding estimated dute of starting any proposed bit, scraper and tubing. Tagg e inhibited iron control HCL a ubing. Rigged up wireline. T tools and rigged down wireline erforate. Rigged up wireline. Spaced out tubing. Nippled d d up. Tested annulus popoff t red tubing to 8000 psi with N2. PF - Morrow). Bled pressure of well in. d packer. TOOH with TCP system rel in. nippled up tree. Set packer bbed tubing dry. Flow testing CONTINUED ON NEXT PAGE: TELEPIKME NO. 505/748