NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION		Supersedes Old
SANTAFE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Seffective 1-1-65
FILE		
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State X Fee
OPERATOR		5. State Oil & Gas Lease No.
		B 10640 7
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		DIR.
1.		7. Unit Agreement Name
OIL GAS WELL	OTHER- Gildcat Re Entry	
2. Name of Operator		8. Farm or Lease Name
Harold L. Rungels		Gladson State
Harold L. Runnels 3. Address of Operator		9. Well No.
P. D. Box 937, Lo	vington, Naw Mexico	1
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER P. 19	80 FEET FROM THE Worth LINE AND 660	FEET FROMildcat
	CINE AND	THE THE PART OF TH
THE X9ST LINE, SECTION	ON 30 TOWNSHIP 16 S RANGE 35 E	NMPM.
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
		Lea
16. Check	Appropriate Roy To Indicate News of M D.	
NOTICE OF IN	Appropriate Box To Indicate Nature of Notice, Rep	
1101102 01 11	TIENTION TO:	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ABANDON		ALTERING CASING
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT I	A DOG AND ABANDONIMENT
		O,B []
OTHER	OTHER	
<ol> <li>Describe Proposed or Completed Op work) SEE RULE 1903.</li> </ol>	perations (Clearly state all pertinent details, and give pertinent date	s, including estimated date of starting any proposed
,		
Plugged as follows:		
Loaded hole with Benta	onite Mud. Set 25 SX plug in and out bas	se of 9 5/8" at 4963. Set
25 3X plug at 300'.	Set 15 5% plug in top of hole with 4" dry	nole marker in top.
	•	4
Sbandoned location.		
, ·		
10 11 1		
10. I nereby certify that the information	above is true and complete to the best of my knowledge and belief.	
1/ 23.	<i>(</i> :	
SIGNED	TITLE Agent	DATE3/5/65
	, , ,	
	<del>//</del>	
14 11	X.	
APPROVED BY THE W. T	Lungar TITLE	DATE