	F NEW MEXICO NERALS DEPARTMENT		
NO. 01 (0+1)			
		5	
SANTA FE	P. O. BOX 2088	- Farm C-103 Revised 10-1-78	
FILE	SANTA FE, NEW MEXICO 87501		
U.S.O.S.		5a. Indicate Type of Lease	
DPERATOR		State Fee K	
		5, State Oil & Gas Lease No.	
	SUNDRY NOTICES AND DEDODED ON THE	XTTT VITTTTTTTTTTTTTTTTTTTTTT	
(D0 H07 L	SUNDRY NOTICES AND REPORTS ON WELLS BE THIS FOR FROPOSALS TO ORILL OR TO DEEPEN OR PLUG BACK TO FREMENT RESERVOIR.	V/////////////////////////////////////	
1.	USE "APP(ICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROF. (.)	VIIIIIIIIIIIIIIIIIIIIIIII	
01L		7. Unit Agreement Name	
2. Name of Operat	SWI1		
U.L.M.	DISPOSAL	8. Form or Lease Name	
J. Address of Ope	ator	MAYME GRAHAM	
P.0	BOX 1544, Lovington, New Mexico 88260	#1	
4. Location of Wel			
	N 660	10. Field and Pool, or Wildcat	
UNIT LETTER	N	Devonian	
W.		VIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	
THE	LINE, SECTION 9 TOWNSHIP 150 RANGE 36E HMPM.		
	15. Elevation (Show whether DF, RT, GR, etc.)	VIIIIIIII/////////////////////////////	
HHHHHi:	3909.5 DF	12. County Lea	
16.			
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
	SUBSEQUENT	REPORT OF:	
PERFORM REMEDIA			
TEMPORARILY ARA	REMEDIAL WORK	ALTERING CASING	
FULL OR ALTER CA	COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT	
	CASING TEST AND CEMENT JOS	<b></b>	
DTHE	OTHER		
17. Describe Prope work) SEE RU	used or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed	
. •			
14 1004	be an pulling tubing from well, seventh joint out has three a	iotes. From.	
	2000 it. down, tubing had a heavy build up of iron sulfide at	la scale on	
	the outside. Fecause scale made frequent cleaning of slip-t,	pe elevators	
	necessary and nigh winds forced a shut down on the 15th of Mc and packer were not out of the well until 15 Nov.	ov. the tabing	
	and packer were not out of the well until 15 NOV.		
17 Nov.	Had pressure tested approximately 8000 ft. of tubing back in	the upli when	
11 1000	a casing bridge was encountered.	che weit when	
	a dabing bridge was encountered.		
18 Nov.	Set 150 bbl. mud pit and utilizing a kill-truck, attempted to	circulate	
	bridged-off scale to the surface. Ever increasing amounts of scale indicated		
	that attempt was exascerbating the problem rather than curing	rit. When	
	packer rubbers circulated to the surface without making heady	yay on numning	
	out the bridge, operations were shut down to wait for rental	equipment.	
		- dathuene	
21 Nov.	Reverse unit and work string of 2" tubing on the lease.		
	Noverse unit and work borring or a bubring on the rease.		
22 Nov	Ran 4.375" O.D. notched collar in well. Tagged and drilled c	wit casing bridge	
EE NOV.			
<u></u>	at 7,520' and second bridge at 7,900'. Pulled several stands	and Shut down.	
18. I hereby certify	that the information above is true and complete to the best of my knowledge and belief.		
X	AP ALL CHA I		
NIGHED T CM	ald The segmenter Time OPERATOR	DATE 9 THY 89	
	Paul Kautz	IAN 9 2 1000	
APPHOVED BY	Geologist TILL	JAN 2 5 1989	
CONDITIONS OF A	PPROVAL, IF ANY:		



JAN 2 5 1989 OCD HOBBS OFFICE

RECOR