	OIL CONSERVATION DIV	ICION	
DISTRIBUTION		ISION	Form C-103
BANTA PE	P. O. BOX 2088		Revised 10-1-78
FILE	SANTA FE, NEW MEXICO 87	501 -	
U.S.G.S.			Sa. Indicate Type of Lease
LAND OFFICE			State Fee 🛴
OPERATOR			5. State Oil & Gas Lease No.
SUNDRY NO	DTICES AND REPORTS ON WELLS		
USE - APPLICATION PC	R PERMIT (FORM C-101) FOR SUCH PROPOSALS.)		
OIL . GAS . O	THER SWD		7. Unit Agreement Name
2, Name of Operator			8. Farm of Lease Name
H&M DISPOSAL	•		MAYME GRAHAM
P.O. BOX 1544, Lovington, New Mexico 88260			#1
4. Location of Well	· · · · · · · · · · · · · · · · · · ·	·····	10. Field and Pool, or Wildcat
UNIT LETTER N. 660	FEET PROM THE S LINE AND	980 FEET FROM	
THE W LINE, SECTION	9TOWNSHIPRANSE	36E	
	15. Elevation (Show whether DF, RT, GR, etc.	1	12. County
3909.5 DF			Lea
16. Check Appr	opriate Box To Indicate Nature of Notic	ce Report of Ot	
NOTICE OF INTER	ITION TO:		REPORT OF:
		(m)	
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK		ALTERING CASING
TEMPORARILY ASANDON	COMMENCE DAILL	.1NE OPHS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND	CEMENT JOS	
	OTHER		
01 HER			
			estimated date of starting any proposed

- 16 Nov. Casing annulus loaded with 5 bols make-up fluid and pressurized. Pressure lost at 250 psi. Packer was pulled up hole and reset at 13,200' and 10,000' to see if old devonion or wolfcamp perforations were taking fluid. Lasth local not be loadeds so tubing less pulled and a large hole found at 13,500'.
- 17 Nov. 9,795' of tubing was run in hole and visually inspected- two joints CE Hydril found with eroded pins. Packer was set and casing loaded but would not hold pressure. A single joint was laid down and tubing stands broken and inspected coming out of the well. Three more joints with eroded pins were found.
- 10 Nov. Tubing was hydrostatically tested back into well. Three joints failed to test. Packer was set at 10,700' and casing held 400 psi for 15 min. Full string of tubing was hung in well.
- 19 Nov. Packer set at 13,567¹, casing loaded and pressurized. No loss of pressure was observed. Backer bypass was opened and 220 bbls of packer fluid was pumped into casing, bypass closed and 20 bbls more fluid loaded in the hole.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

overes & M Hanod	TITLE	OPERATOR	DATE 20 NOV 87
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR	11TLE	······································	NOV 2 4 1987
CONDITIONS OF APPROVAL, IF ANY:			