

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	3
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator D. W. St. Clair		8. Farm or Lease Name Graham
3. Address of Operator 501 First Nat'l Bank Bldg., Midland, Texas 79701		9. Well No. 1
4. Location of Well UNIT LETTER N 660 FEET FROM THE South LINE AND 1980 FEET FROM West LINE, SECTION 9 TOWNSHIP -15-8 RANGE -36-E NMPM.		10. Field and Pool, or Wildcat Caudill Devonian
15. Elevation (Show whether DF, RT, GR, etc.) 3909 GR		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging operations to begin approx. September 4, 1970

1. Load hole with brine water & gel
2. Set 50 Sx Cement Plug on Bottom
3. Set 25 Sx Cement Plug in & out of 5 1/2" Casing Stub
4. Set 25 Sx Cement Plug Base of 8 5/8" Casing
5. Set 25 Sx Cement Plug in & out of 8 5/8" Casing Stub
6. Set 25 Sx Cement Plug Base of 11 3/4" Casing
7. Set 10 Sx Cement Plug at Surface

T.D. of Well 13,600'

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>George Van Hise</i></u>	TITLE Agent	DATE Sept. 2, 1970
APPROVED BY <u><i>[Signature]</i></u>	TITLE SUPERVISOR DISTRICT	DATE SEP 10 1970
CONDITIONS OF APPROVAL, IF ANY:		