

NUMBER COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL GAS
PERORATION OFFICE	
OPERATOR	

(Form C-102)  
(Revised 7/1/52)

# NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

## MISCELLANEOUS NOTICES

strict Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL		NOTICE OF INTENTION TO PLUG BACK	X	NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE	X	NOTICE OF INTENTION TO SHOOT (Nikro)	
NOTICE OF INTENTION TO GUN PERFORATE		NOTICE OF INTENTION (OTHER) TO PERFORATE	X	NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION  
SANTA FE, NEW MEXICO

Roswell, New Mexico

October 6, 1961

(Place)

(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the.....

Shell Oil Company State GA Well No. 3 in M  
(Company or Operator) Lessee (Unit)  
SW 1/4 SW 1/4 of Sec. 16, T15S, R. 36E, NMPM., Caudill-Devonian Pool  
(40-acre Subdivision)  
Lea County.

## FULL DETAILS OF PROPOSED PLAN OF WORK (FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

### PROPOSED OPERATION:

1. Pull rods, pump & tubing.
2. Run GR/N w/CCL from 11,000' to 4750'. Run cement bond log from 11,000' to top of cement.
3. If cement bond is satisfactory, set CIBP at 10,800' & cap w/cement. ✕
4. Run tubing. Displace water and load hole w/oil.
5. Swab fluid level down to 3500' - 4000'.
6. Perforate intervals to be selected from GR/N log between 10,500' - 10,600'.  
Use lubricator.
7. Swab test.
8. If necessary, acidize w/2000 gallons 15% NEA.
9. Swab test and place on production.

Approved..... 19.....  
Except as follows:

Approved  
OIL CONSERVATION COMMISSION

By.....  
Title.....

Shell Oil Company

Company or Operator

By..... R. A. Lowery  
Position..... District Exploitation Engineer

Send Communications regarding well to:

Name..... Shell Oil Company  
Address..... Box 1858, Roswell, New Mexico