

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-1044
7. Unit Agreement Name -
8. Farm or Lease Name State GA
9. Well No. 7
10. Field and Pool, or Wildcat Caudill-Permo Penn.
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>
2. Name of Operator Shell Oil Company
3. Address of Operator P. O. Box 1858, Roswell, New Mexico 88201
4. Location of Well UNIT LETTER B 660 FEET FROM THE north LINE AND 2310 FEET FROM THE east LINE, SECTION 16 TOWNSHIP 15-S RANGE 36-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3917' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Ran 2" tubing to PBTD.
2. Spotted 75 sx over perforations 10,190'-10,531'.
3. Plug did not hold. Reset second plug 50 sx slo-set.
4. Shot casing at 9015'. Pulled 231 jts. (9010') 5 1/2" casing.
5. Set 25 sx on top of casing stub.
6. Set 25 sx cement plugs at the following depths:
8118', 7409', 6206', 4740'
10 sx at surface.
7. Erected prescribed 4" x 4' marker.
8. Plugged and Abandoned July 6, 1965.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Original Signed By **R. J. Doubek** TITLE **Division Mechanical Engineer** DATE **July 6, 1965**
APPROVED BY *Lester A. Clements* TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: