NO. OF COPIES RECEIVED			Form C-103
DISTRIBUTION		HOBBS OFFICE O.C.C	Supersedes Old
SANTA FE	NEW MEXICO OIL	CONSERVATION COMMISSION	• C-102 and C-103 Effective 1-1-65
FILE			
U.S.G.S.		Apr 4 8 os M'S	5a. Indicate Type of Lease
LAND OFFICE	4-0CC		State 🕱 🛛 🛛 Fee
OPERATOR	l-File		5. State Oil & Gas Lease No.
			E-22 47
SUN (DO NOT USE THIS FORM FOR USE "APPL	IDRY NOTICES AND REPOR PROPOSALS TO DRILL OR TO DEEPEN OF ICATION FOR PERMIT -" (FORM C-101)	TS ON WELLS a plug back to a different reservoir. for such proposals.)	
01L GAS			7. Unit Agreement Name
	OTHER-		
2. Name of Operator			8. Farm or Lease Name
Tidewater 011	State "AE"		
3. Address of Operator			9. Well No.
Box 249, Hobbs	, New Mexico		1
4. Location of Well			10. Field and Pool, or Wildcat
UNIT LETTER	FEET FROM THE	lest Line and 660 FEET FRO	Dean Permo Penn
THE _South LINE, SE		15-S RANGE 36-E NMPN	
		vhether DF, RT, GR, etc.)	12. County
	38	66 GR	Lea
Chec	k Appropriate Box To Indic INTENTION TO:	cate Nature of Notice, Report or O SUBSEQUEN	ther Data
PERFORM REMEDIAL WORK	PLUG AND ABANDO	IN REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
		OTHER	Π
OTHER	······································	[]	
17 Describe Proposed or Completed	Operations (Clearly state - II	ent details, and give pertinent dates, includin	

work) SEE RULE 1103.

Pulled rods and tubing. Ran 5-3/4" gauge ring, stopped at 5866'. Worked loose. Ran 6" bit to 5866'. Could not go deeper. Pulled and ran 5-1/8" bit to 6510'. Did not touch anything. Pulled bit. Ran tie-in log. Perforated with one jet shot per foot from 10428-42', 10658-66 and 10674-80'. Ran Lynes straddle packers 50.5' apart. Set bottom 5" OD Lynes packer at 10697' and top packer at 10647'. Inflated with acid. Treated with 2604 gals 15% NE with double inhibitor. Attempted to release packers. Could not. Rigged up McCullough to attempt to shoot two holes in bottom packer to deflate. Could not get below 10578'. While trying to work thru tight spot, lost weight from 72000# back to 60000#. Picked up and tubing free. Pulled out of hole with McCullough. Pulled tubing. Left two joints tubing plus Lynes packers in hole. Picked up 2-7/8" DP. Ran 5-1/4" OD swage; one 4-1/4" DC, 5-3/4" swage and swaged out to 5-3/4", no drag. Re-covered all fish. Ran 2-7/8" (2434"), balance 2-3/8" and set at 10671', Guiberson packer at 5846'. Swabbed back load fluid, ran rods and put back on pump.

-	Original Signed By	complete to the best of my knowledge and belief.		
IGNED	O. L. WADE	TITLE Area Supt.	DATE 4-1-66	
PROVED BY		TITLE	DATE	

APR 4 8 OS AM "66

· .