

Submit 3 Copies To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 1301 W. Grand Ave., Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-103
 Revised March 25, 1999

WELL API NO.
30-025-03737

5. Indicate Type of Lease
 STATE FEE

6. State Oil & Gas Lease No.
E 9335-5

7. Lease Name or Unit Agreement Name:
State "T"

8. Well No.
4

9. Pool name or Wildcat
Townsend Permo Upper Perm

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
 Oil Well Gas Well Other

2. Name of Operator
Proghorn Mgt. Corp.

3. Address of Operator:
P.O. Box 1772 Hobbs, N.M. 88241

4. Well Location
 Unit Letter **K** : **4620** feet from the **South** line and **1885** feet from the **West** line
 Section **6** Township **16-S** Range **36-E** NMPM **Lea** County


10. Elevation (show whether DR, RKB, RT, GR, etc.)
3958'

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Move in and rig up.
 2. POOH with tubing.
 3. Nipple up to 5 1/2" casing. Stretch, cement and pull casing.
 4. Spot cement plug 50' in and out of string. WOC and tag.
 5. Spot 100' cement plug at intermediate casing shoe. tag
 6. Spot 100' cement plug at top of salt. Tag
 7. Spot 25 sx on 100' cement plug at 13 3/8" casing shoe. tag
 8. Spot 10 sx surface plug.
 9. Exact day hole marker. Clean location.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *G.A. Baben* TITLE Partner DATE 04/19/02

Type or print name G. A. Baben Telephone No. 505-343-9176
 (This space for State use)

APPROVED BY _____ TITLE _____ ORIGINAL SIGNED BY _____ DATE _____
 Conditions of approval, if any: _____ PAUL F. KAUTZ APR 19 2002
 PETROLEUM ENGINEER

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

S
 C

[Handwritten signature]