

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	39-025-03737
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	E 9335-5
7. Lease Name or Unit Agreement Name	STATE "T"
8. Well No.	4
9. Pool name or Wildcat	Permian Upper TOWNSEND-WOLF CAMP Penn

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator BABER WELL SERVICING COMPANY
3. Address of Operator P.O. BOX 1772 HOBBS, NM 88241	4. Well Location Unit Letter K : 4620 Feet From The South Line and 1885 Feet From The West Line Section 6 Township 16-S Range 36-E NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3958'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) M.I.R.U.
- 2) Install 6" - 900 B.O.P.
- 3) Unable to unseat anchor at 10,400'.
- 4) Received permission from NMOCC to cut tbg.
- 5) Cut tbg @ 10,400'.
- 6) Tag plug @ 10,000'.
- 7) Set 35 sks plug @ 7,500'.
- 8) Tag plug @ 7,500'.
- 9) File application to make disposal well
- 10) Shut in well
- 11) Temporarily abandon well

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Guy Baber TITLE CHRMN OF BOARD DATE 10/18/93
TYPE OR PRINT NAME G.A. BABER, JR. TELEPHONE NO. 392-5516

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY

TITLE

OCT 21 1993
DATE

CONDITIONS OF APPROVAL, IF ANY: