will assure that these wellbores will not serve as a conduit for migration of injected wells shown on Exhibit "D", the applicant shall re-plug said wells in a manner which fluid to the satisfaction of the supervisor of the Hobbs district office of the Division. (5) Prior to initiating injection operations within one-half mile of any of the

EXHIBIT "D" CASE NO. 10154 ORDER NO. R-9431

INADEQUATELY PLUGGED AND ABANDONED WELLS

Tidewater Associated Oil Co. Cities Service Getty Oil Co. Getty Oil Co. Magnolia Petroleum Co.	Operator
H.T. Monteith State AE State "M" State "P" State "R"	Lease
ω v, ω p, <u>-</u>	Well No.
1650' FSL - 2335' FWL 3630' FNL - 4290' FEL 1650' FSL - 1650' FEL 330' FSL - 330' FWL 660' FNL - 660' FEL	Location
25-16-36 36-16-36 36-16-36 32-16-37 02-17-36	Sec-Twp-Rge