

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-4287	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name West Lovington Unit
2. Name of Operator TEXACO Inc.	8. Farm or Lease Name West Lovington Unit
3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240	9. Well No. 1
4. Location of Well UNIT LETTER M 660 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 33 TOWNSHIP 16-S RANGE 36-E NMPM.	10. Field and Pool, or Wildcat Lovington San Andres West
15. Elevation (Show whether DF, RT, GR, etc.) 3907' (GR)	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:



SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. RIGGED UP.
2. RUN FREE POINT AND CUT 5 1/2" CSG @ 2070'. WOULD NOT PULL.
3. SET CEMENT RETAINER @ 1891'. SQUEEZED CUT @ 2070' W/200 SX CLASS H CEMENT AND SPOT 1-1/2 BBL CEMENT ON TOP OF RETAINER.
4. CUT 5 1/2" CSG @ 800' AND PULL.
5. CUT 8 5/8" CSG @ 740' AND PULL.
6. SPOT 75 SX CEMENT PLUG FROM 808'- 622'.
7. SPOT 75 SX CEMENT PLUG FROM 372'- 266'.
8. SPOT 10 SX CEMENT PLUG @ SURFACE.
9. CLEAN LOCATION. INSTALL DRY HOLE MARKER. WELL PLUGGED & ABANDONED 7-5-84.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED 	TITLE ASST DIST MANAGER	DATE 7-23-84
APPROVED BY 	TITLE OIL & GAS INSPECTOR	DATE APR 10 1987
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

JUL 24 1984

OFFICE