

## NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

## MISCELLANEOUS NOTICES

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of notice by checking below:

NOTICE OF INTENTION TO TEST CASING SHUT-OFF	<input checked="" type="checkbox"/>	NOTICE OF INTENTION TO SHOOT OR CHEMICALLY TREAT WELL	
NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING	
NOTICE OF INTENTION TO REPAIR WELL		NOTICE OF INTENTION TO PLUG WELL	
NOTICE OF INTENTION TO DEEPEN WELL			

Odessa, Texas

November 26, 1938

Place

Date

OIL CONSERVATION COMMISSION,  
Santa Fe, New Mexico.

Gentlemen:

Following is a notice of intention to do certain work as described below at the

Barnsdall Oil Company

State

Well No. 41

in 22/4

Company or Operator

Lease

of Sec. 33, T. 16N, R. 54E, N. M. P. M., Lovington Field,

Lee

County.

## FULL DETAILS OF PROPOSED PLAN OF WORK

FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS OF THE COMMISSION

We wish to test the 8 5/8" casing for water shut off on the above well November 26, 1938 at 8:00 P.M. The test will be made by building up a pressure of 1000# and leaving set 30 minutes, as per rules and regulations.

Approved \_\_\_\_\_, 19\_\_\_\_  
except as follows:

NOV 30 1938

Barnsdall Oil Company

Company or Operator

By

Lawrence Mills

Position

Production Clerk

Send communications regarding well to

OIL CONSERVATION COMMISSION,

Name

Barnsdall Oil Company

By

Rosa Walker R.M.

Address

Odessa, Texas - Box 4472

Title

OIL &amp; GAS INSPECTOR

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000