

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-03771
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Texaco Exploration & Production, Inc.		6. State Oil & Gas Lease No. B-7316
3. Address of Operator P.O. Box 3109 Midland, Texas 79702		7. Lease Name or Unit Agreement Name: Skelly "S" State
4. Well Location Unit Letter <u>P</u> : <u>990</u> feet from the <u>South</u> line and <u>330</u> feet from the <u>East</u> line Section <u>35</u> Township <u>16S</u> Range <u>36E</u> NMPM Lea County		8. Well No. 2
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. Pool name or Wildcat Lovington-ABO

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. RIH Tag CIBP @ 8145, spot 25 sxs. plug 8145 to 7945 (ABO) Tag @ 7903
2. Displace hole w/MLF, 9.5# Brine w.25# gel P/BBL
3. Spot 25 sxs. plug 6100 to 5900 (Glorieta)
4. Spot 25 sxs. plug 4600 to 4400 (Queen) Tag @ 4328
5. Cut 5 1/2" csg. @ 3350 L/D csg.
6. Spot 135 sxs. plug 3400 to 3000 (8 5/8 shoe, Yates, B-Salt, Stub) Tag @ 2881
7. Spot 50 sxs. plug 2400 to 2200 (T-Salt) Tag @ 2173
8. Spot 50 sxs. plug 300 to 150 (13 3/8 shoe) Tag @ 157 (OK with OCD)
9. CIRC cmt. 30 to surf. w/15 sxs., install dry hole marker 2/27/02

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jimmy Bagley TITLE MANAGER DATE 2/27/02

Type or print name Jimmy Bagley Telephone No. 915 683-4997

APPROVED BY Billy E. Paulsen TITLE COMPLIANCE OFFICER JUNE 13 2002
Conditions of approval, if any: 6 WW