

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐	WELL API NO. 30-025-03771
2. Name of Operator Chevron - Texaco, Corporation	5. Indicate Type of Lease STATE ☒ FEE ☐
3. Address of Operator P. O. Box 3109, Midland, TX 79702	6. State Oil & Gas Lease No. B-7316
4. Well Location Unit Letter P : 990 feet from the South line and 330 feet from the East line Section 35 Township 16S Range 36E NMPM Lea County	7. Lease Name or Unit Agreement Name: Skelly "S" State
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	8. Well No. 2
	9. Pool name or Wildcat Lovington - ABO

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. RIH Tag CIBP @ 8145'. Spot 25 Sx plug 8145'-7945' (ABO) WOC Tag
2. Displace hole w/MLF, 9.5# Brine w/25# gel P/BBL
3. Spot 25 Sx plug 6100'-5900' (Glorieta)
4. Spot 25 Sx plug 4600'-4400' (Queen) WOC Tag
5. Cut 5 1/2" Csg @ 3350' L/D Csg.
6. Spot 135 Sx plug 3400'-3000' (8 5/8" shoe, Yates, B-Salt Stub) WOC Tag
7. Spot 50 Sx plug 2400'-2200' (T-Salt) WOC Tag
8. Spot 50 Sx plug 300'-150' (13 3/8" shoe) WOC Tag
9. 10 Sx surface, Install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James T. Corbitt TITLE OPERATIONS SUPERVISOR DATE 12/2/01
Type or print name JAMES T. CORBITT Telephone No. 567-3622
(This space for State use)

APPROVED BY Chris TITLE NATURAL GAS DATE DEC 11 2001
Conditions of approval, if any: