

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-03771
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-7316
7. Lease Name or Unit Agreement Name	
Skelly "S" State	
8. Well No.	2
9. Pool name or Wildcat	
Lovington Abo	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
3859' DF	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Texaco Exploration and Production Inc.
3. Address of Operator P.O. Box 730 Hobbs, New Mexico 88240	8. Well No. 2
4. Well Location Unit Letter P : 990 Feet From The South Line and 330 Feet From The East Line Section 35 Township 16-S Range 36-E NMPM Lea County	9. Pool name or Wildcat Lovington Abo
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3859' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Test Casing for TA <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Conducted casing integrity test on the above well.
2. Tested 5 1/2" casing from surface to CIBP @8145' to 500# for 30 minutes. Held OK.
3. Request temporarily abandon well status through 2-7-97.

(ORIGINAL CHART DELIVERED TO NMOCD)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M.C. Duncan TITLE Engineer's Assistant DATE 2-7-92
TYPE OR PRINT NAME M.C. Duncan TELEPHONE NO. 393-7191

(This space for State Use)

APPROVED BY JERRY SEXTON
SUPERVISOR


APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

This Approval of Temporary
Abandonment Expires

FEB 13 1992

2-7-97



PRINTED IN U.S.A.

TEXAS
INSTRUMENT ENGINEERS

TEXACO, Inc.

A-35-16-36

WATER NUMBER

TIME PUT ON

DATE PUT ON

1/31/92

TIME TAKEN UP

DATE TAKEN UP

1-31-92

BR-2221

Q-1000-8

Skelly's State #2

RECEIVED

FEB 09 1992

7-30-92
+4 OILFIELD
MAG NEWELLIANUS
UNIT #12
SERVICE