

OIL CONSERVATION
 P. O. BOX 2088
 SANTA FE, NEW MEXICO 87501

Form O-103
 Revised 10-1-78

DATE SUBMITTED	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No.	
B7316	

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
 USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator
 Texaco Producing Inc.

Address of Operator
 P.O. Box 728, Hobbs, New Mexico, 88240

Location of Well
 UNIT LETTER P 990 FEET FROM THE South LINE AND 330 FEET FROM
 THE East LINE, SECTION 35 TOWNSHIP 16S RANGE 36E NMPM.

7. Unit Agreement Name	
8. Form or Lease Name	State <u>High</u>
9. Well No.	2
10. Field and Pool, or Wildcat	Lovington Abo
11. Elevation (Show whether DF, RT, GR, etc.)	3859' DF
12. County	Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

FORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
REPAIR OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	OTHER <u>Temporarily abandon</u> ☒

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

04-18-86 MIRU. Pull and lay down rods and pump. Pull tubing.

04-19-86 Set 5 1/2" Howco EZ Drill BP on wireline @ 6145' (top perforation at 8243'). Run tubing open ended, tag BP. Circulate packer fluid. Pull and lay down tubing. Shut well in. RD.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE District Supervisor DATE 05-12-86

ORIGINAL SIGNED BY JERRY SEXTON
 DISTRICT 1 SUPERVISOR

DATE MAY 20 1986

Expiring 5-19-87

RECEIVED
MAY 13 1966
U.S. AIR FORCE
JOINT STAFF