

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

11:05 AM DISTRICT OFFICE OF O. C. C.
 NEW MEXICO OIL CONSERVATION COMMISSION
 JUN 10 10 30 AM 1969

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-7766
7. Unit Agreement Name
8. Farm or Lease Name State AE
9. Well No. 2
10. Field and Pool, or Wildcat Lovington Abo
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
 USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Cities Service Oil Company
3. Address of Operator P. O. Box 69 - Hobbs, New Mexico 88240
4. Location of Well UNIT LETTER L , 3630 FEET FROM THE North LINE AND 4290 FEET FROM THE East LINE, SECTION 36 TOWNSHIP 16S RANGE 36E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3845 D.F.

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well has been plugged and abandoned in the following manner:

1. Set cast iron retainer at 3988.
2. Mix and displace 555 sack cement below retainer.
3. Cut and recovered 3700' of 5½" casing.
4. Displaced 50 sack cement plug @ 5½" casing stub 3750-3560. Displaced 50 sack plug ½ in and ½ out of 8 5/8" casing 3400-3240.
5. Set 10 sack plug in top of 8 5/8 from G.L. to 30' and installed 4" pipe dry hole marker.
6. Cleaned location of all equipment and debris - pits have been filled and leveled.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED _____ TITLE **District Office Manager** DATE **June 6, 1969**

APPROVED BY *John W. Runyan* TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: