

Submit 3 Copies To Appropriate District  
Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO.

30-025-03791

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:

State "R"

8. Well No.

5

9. Pool name or Wildcat

Lovington ABO 40470

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator Chevron USA, Inc.

3. Address of Operator 15 Smith Rd. Midland, Tx 79705

4. Well Location

Unit Letter N : 330 feet from the south line and 2310 feet from the west line

Section 36 Township 16-S Range 36-E NMPM County Lea

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. Notify OCD 24hrs prior to MI & RU
2. Set 5 1/2 CIBP @ 8125, spot 25sx plug 8125-7925(ABO) WOC Tag.
3. Displace hole w/MLF, 9.5 # Brine w/25 # Gel P/BBL.
4. Spot 25sx plug 6800-6600(Clearfork)
5. Spot 25sx plug 6000-5800(Glorietta)
6. Perf 4 holes @ 3400, sqz 75sx plug 3400-3100(8 5/8 shoe, Yates, B-salt) WOC Tag.
7. Perf 4 holes @ 2100, sqz 50sx plug 2100-1900(T-salt) WOC Tag.
8. Perf 4 holes @ 290, sqz 175sx plug 290-surf(5 1/2X8 5/8X 13 3/8)(13 3/8 shoe)WOC Tag.
9. Install dry hole marker.

THE COMMISSION MUST BE NOTIFIED 24  
HOURS PRIOR TO THE BEGINNING OF  
PLUGGING OPERATIONS FOR THE C-103  
TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE G. R. Bledsoe TITLE HES Specialist DATE 11/1/2002

Type or print name G. R. Bledsoe Telephone No. 915.687.7153

(This space for State use)

APPROVED BY GARY W. WINK DATE NOV - 7 2002  
Conditions of approval, if any: OC FIELD REPRESENTATIVE II/STAFF MANAGER