Box 1957, Hobbs, New Mexico

## NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS #1 7:23

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is comp ıal ir

	Indicate Nature of Repo	rt by Checking Be	How	
REPORT ON BEGINNING DRILLING OPERATIONS	REPORT ON RESUL OF CASING SHUT-0		REPORT ON REPAIRING WELL	L
REPORT ON RESULT OF PLUGGING WELL	REPORT ON RECOM	MPLETION	REPORT ON (Other)	
	July 6.	1954	Hobbs, New M	(Place)
Following is a report on the work	done and the results obtained	under the heading i	noted above at the	
Shell Oil Company (Company or O	Buckley "B"			
Corbett Drilling Compa				
r 14-3 , r 37-8 , nmpm.,	Denton	Pool,	Lea	County
The Dates of this work were as folows:	tu	ly 3, 1954		
Notice of intention to do the work (	(was not) submitted on Form (	C-102 on		10
Notice of intention to do the work (		0-10 <b>L</b> 011	(Cross out incorrect words)	, 19
and approval of the proposed plan (				
DEIA	ILED ACCOUNT OF WORK D	ONE AND RESU	LIS OBTAINED	
* ***				_
Kon 10 4/71 of E	1/2" cast ne and came:		72' with 750 sack	_ 1074
Mail 12,541 OL 5	my	nted at 12,5		a the Ber
	at coment. After WOC	•		_
and 100 sacks ne	at cement. After WOC	27 hours sta	retch test indica	ted freeze
and 100 sacks ne	at sement. After WOC 48 h	27 hours strough	retch test indica	ted freeze
and 100 sacks ne	at coment. After WOC 48 h	27 hours strough	retch test indica	ted freeze
and 100 sacks ne	at sement. After WOC 48 h	27 hours strough	retch test indica	ted freeze
and 100 sacks nepoint to be at 70 minutes. Test 0	at sement. After WOC 48 h	27 hours strough	retch test indica	ted freeze
and 100 sacks nepoint to be at 70 minutes. Test 0	at sement. After WOC 48 h	27 hours strough	retch test indica	ted freeze
and 100 sacks nepoint to be at 7 minutes. Test OK.	at cement. After WOC 48 how was and the same and the same and the same art. Shell (	27 hours strough	retch test indicar sasing with 1500 ; t with 1000 psi fo	ted freeze pei for 30 or 30 mimutes.
and 100 sacks nepoint to be at 74 minutes. Test 0. Test 0. Witnessed by P. W. Stew (Name)	at cement. After WOC 48 how.  W. Drilled shoe and the state of the shoe and the sho	27 hours strough tested comments tested comments tested comments the comments of the company of	Drilling the information given about the information given about the control of t	psi for 30 or 30 minutes.  Foreman e) ove is true and complete Original signed by
and 100 sacks nepoint to be at 7.  minutes. Test 0.  Test OK.  Witnessed by P. W. Stewn (Name)	at cement. After WOC 48 how.  W. Drilled shoe and the state of the shoe and the sho	27 hours strough tested comments  Company  Company  I hereby certify that	Drilling the information given about the information given about the control of t	psi for 30 or 30 minutes.  Foreman
and 100 sacks ne point to be at 7. minutes. Test 0. Test 0. Test 0. Witnessed by P. W. Stew (Name)	at cement. After WOC 48 how.  W. Drilled shoe and the state of the shoe and the sho	27 hours strough tested company  Company  I hereby certify the to the best of my keeps	Drilling (Title the information given about the information given gi	psi for 30 or 30 minutes.  Foreman e) ove is true and complete Original signed by F. D. Leigh

(Title)