1. Type of Well: MET XX

2. Name of Operator

3. Address of Operator

Section

PERFORM REMEDIAL WORK

TEMPORARILY ABANDON

PULL OR ALTER CASING

4. Well Location

11.

DISTRICT P.O. Box 1980, Hobbs, NM 88240

DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410

## OIL CONSERVATION DIVISION

DISTRICT II P.O. Drawer DD, Artesia, NM \$8210

(NENE)

NOTICE OF INTENTION TO:

S & J OPERATING COMPANY

27

SUNDRY NOTICES AND REPORTS ON WELLS ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

P.O. BOX 2249, WICHITA FALLS, TEXAS 76307-2249

Energy, Minerals and Natural Resources Department	Eco as Coj (13 Revised 1-1-29
OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088	WELL API NO. 3002505163
\$4210 Salita 1 e, New Mexico 8/304-2088	5. Indicate Type of Lease
M 87410	6. State Oil & Gas Leese No.
RY NOTICES AND REPORTS ON WELLS M FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A ENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name (8910087370)
GAS OTHER	DENTON NORTH WOLFCAMP UNIT TRACT 13
G COMPANY	8. Well No.
WICHITA FALLS, TEXAS 76307-2249	9. Pool name or Wildow DENTON WOLFCAMP
: 990 Feet From The NORTH Line and 330	Feet From The EAST Line
NENE) Township 14-S Range 37-E  10. Elevation (Show whether DF, RKB, RT, GR, atc.) 3834 DF	NMPM LEA County
Check Appropriate Box to Indicate Nature of Notice, R OF INTENTION TO: SUB	eport, or Other Data SEQUENT REPORT OF:
PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
CHANGE PLANS COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
CASING TEST AND CE	MENT JOB
OTHER:	
sted Operations (Clearly state all pertinent details, and give pertinent dates, included	ling estimated date of starting any proposed
NG WELL, AS OF 4-1-93. On 10-9-92 set CIBP at water treated with corrosion inhibitor. On 1	: 9300' and circulated 10-12-92 dumped 4 sacks

OTHER: OTHER:\_ 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclu work! SEE RULE 1103.

Last PRed 11-88

SHUT IN PRODUCING WELL, AS OF 4-1-93. On 10-9-92 set CIBP a well with salt water treated with corrosion inhibitor. On of cement on CIBP.

Procedure for obtaining temporarily abandoned status:

1. Pressure test casing to 500 psig for 30 minutes with a pressure drop of not more than 10% for 30 minutes.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
Manager of OPerations  TYPE OR FIRST NAME PEYTON S. CARNES, JR.	3-17-93 (817) 723-2166 TELEPHONE NO.
(This space for State Use) CRUGINIAL SERVICE BY JERRY SEXTON BY CHICK I SUPERVISOR	MAR 2 3 1993
APPROVED BY	DATE

RECEIVED

OCD HOBBS OFF