NO. OF COPIES RECEIVED	\P () $(x,y) = (x,y)$ () $(x,y) = (x,y)$	
	4	Form C-103
DISTRIBUTION	4	Supersedes Old C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE	<u>.</u>	• • • •
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State Fee. X
OPERATOR	1	5. State Oil & Gas Lease No.
	J	5. State Off & Gds Ledse No.
SIN ID		
SUNDI DO NOT USE THIS FORM FOR PR	RY NOTICES AND REPORTS ON WELLS	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		
OIL GAS		7. Unit Agreement Name
WELL WELL	OTHER- P & A	
2. Name of Operator		8. Farm or Lease Name
· Atlantic Rich	field Company	B.C. Dickinson A-34
3. Address of Operator		
P.O. Box 1978	, Roswell, New Mexico 88201	9. Well No.
4. Location of Well	7 RODWCII7 New President Gozdi	2
	1650	10. Field and Pool, or Wildcat
UNIT LETTER,	1650 South LINE AND 330 FEET	FROM Denton-Devonian
East	34 14-S 37-E NAME NAME NAME NAME NAME NAME NAME NAM	
THE LINE, SECTI	ON TOWNSHIP RANGEN	MPM. (
mmmmm	15 Planette (C)	
	15. Elevation (Show whether DF, RT, CR, etc.)	12. County
		Lea ()
Check	Appropriate Box To Indicate Nature of Notice, Report or	0.1 5
NOTICE OF I		
NOTICE OF II	SUBSEQU	ENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
		_
OTHER	OTHER	
OTREA		
17. Describe Proposed or Completed Or	erations (Clearly state all pertinent details, and give pertinent dates, inclu	7.
work) SEE RULE I fo3.	the perturbation of the perturbation details, and give perturbation dates, inclu	aing estimated date of starting any propose
ml. (
This well has	been plugged and abandoned in the fol	llowing manner:
	•	-
Set DR plug i	n 415-D packer @ 12,000' and capped w/	/2
Si i se si	in 415-b packer @ 12,000 and capped wy	/2 sx or cement.
Shot off 5%"	casing @ 7519' WLM. Pulled 230 jts (a	approx 7500') of
5½" casing.	Set 30 sk cmt plug from 7562-7438'; se	et 30 sk cement
nlug 6215_613	51. got 30 gle goment ml 4200:46001	of 50 BK Cement
prug 0215-015	5'; set 30 sk cement plug 4769-4689';	placed 10 sk
cement plug i	n top of well. Installed dry hole mar	rker. 13-3/8"
and 9-5/8" ca	sing strings remain intact. 9# mud wa	as used to spot
all pluge W	ell P & A 6/4/71.	doca to spot
orr progs. W	EII F & A 0/4//1.	
•		
<i>E.E.</i> !		
Your office w	ill be notified when this location is	re ady
for inspection	1.	
•		
8. I hereby certify that the information	above is true and complete to the best of my knowledge and belief.	
///XIAITA//	nier nei	c 100 100
IGNED - NYTHICHE	Dist. Drlg. Superviso	or 6/29/71
	. 00	
2 All	ニュー・F F J	
II dun a - >	Y /// OLG GAS INSPECTOR	E A STATE OF THE S
PPROVED BY	· INODE	MAR \$ 1972
ONDITIONS OF APPROVAL, IF ANY:	THEE THE	MAR \$ 872

RECEIVED

JUN3 1971
OIL CONSERVATION COMM.
HOBBS, N. M.