

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

| |
|---|
| WELL API NO. 30-025-05190 |
| 5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> |
| 6. State Oil & Gas Lease No. 623-3 |
| 7. Lease Name or Unit Agreement Name T. D. Pope |
| 8. Well No. 5 |
| 9. Pool name or Wildcat Denton Devonian |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) |

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

| |
|---|
| 1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Horizontal |
| 2. Name of Operator Collins & Ware, Inc. |
| 3. Address of Operator 508 W. Wall, Suite 1200, Midland, Texas 79701 |
| 4. Well Location Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The East Line Section 35 Township 14S Range 37E NMPM Lea County |

| | |
|---|---|
| 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data | |
| NOTICE OF INTENTION TO: | SUBSEQUENT REPORT OF: |
| PERFORM REMEDIAL WORK <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> |
| OTHER: <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| | CASING TEST AND CEMENT JOB <input type="checkbox"/> |
| | OTHER: <input type="checkbox"/> |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set CIBP @ 11,980 w/ 35' cement on top. Set CIBP @ 4790' w/ 35' cement on top. Retrieve 5 1/2" casing - 4550'. Spot 50 sx cement plug from 4650' to 4418'. Spot 60 sx cement plug from 530' to 330'. Spot 10 sx cement @ surface. Install dry hole marker and clean up location per NMOCD requirements.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dianne Sumrall TITLE Production Analyst DATE 5/3/94

TYPE OR PRINT NAME Dianne Sumrall

TELEPHONE NO. 915-687-3435

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAY 11 1994

JOHN HUBBS
OFFICE