

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-05195
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name T. D. Pope
2. Name of Operator Polaris Production Corp.	8. Well No. 21
3. Address of Operator P. O. Box 1749, Midland, TX 79702-1749	9. Pool name or Wildcat Wildcat

4. Well Location Unit Letter <u>A</u> : <u>660</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>35</u> Township <u>14-S</u> Range <u>37-E</u> NMPM Lea County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3818 DF
---	---

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: (Test San Andres) <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set CIBP @ 11,950'. Dump 3 sx. cement on top.
2. Circ. hole w/ 9.5# mud.
3. Spot 50 sx. cement plug @ 9,000 - 9,500'.
4. Spot 50 sx. cement plug @ 6,100 - 6,600'.
5. Shut well in waiting on completion rig.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Garry Payne TITLE Production Mgr. DATE 12-9-98
TYPE OR PRINT NAME Garry Payne TELEPHONE NO. 915/684-8248

(This space for State Use)

APPROVED BY DATE TITLE DATE
CONDITIONS OF APPROVAL, IF ANY: