

Submit 3 Copies To Appropriate District
Office

District I

1625 N. French Dr., Hobbs, NM 87240

District II

811 South First, Artesia, NM 87210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

2040 South Pacheco

Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO.

30-025-05198

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:

Denton North Wolfcamp Unit
Tract 6

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Stephens & Johnson Operating Co.

3. Address of Operator

P O Box 2249, Wichita Falls, TX 76307-2249

8. Well No.

26

9. Pool name or Wildcat

Denton Wolfcamp

4. Well Location

Unit Letter J : 1980 feet from the South line and 2180 feet from the East line

Section 35 (NW SE) Township 14S Range 37E NMPM County Lea

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

3799 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Well has been temporarily abandoned since 1-1-93. Will plug and abandon.

See attached plugging procedure.

THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE C-103
TO BE APPROVED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE _____ TITLE Manager of Operations DATE 6-25-02

Type or print name Peyton S. Carnes, Jr.

Telephone No. 940-723-2166

(This space for State use)

APPROVED BY _____ TITLE _____

Conditions of approval, if any:

DATE JUL 30 2002

ORIGINAL SIGNED BY

GARY W. WINK


OO FIELD REPRESENTATIVE/STATE MANAGER

DENTON NORTH WOLFCAMP UNIT WELL NO. 6-26

Plugging Procedure:

- 1) Set 5 1/2" CIBP @ 9100' with 35' cement on plug.
- 2) Run tubing to 9065', tag plug and load hole with 9.5# mud laden salt water.
- 3) Spot 25 sack plug @ 7300' in 5 1/2" casing.
- 4) Spot 30 sack plug 50' inside of 5 1/2" liner (4660') to 4532' inside of 7 5/8" casing. Tag plug.
- 5) Spot 25 sack plug at 3150' in 7 5/8" casing.
- 6) Spot 25 sack plug at 2200' in 7 5/8" casing.
- 7) Perforate 7 5/8" casing at 130', run tubing to 510' and pump 200 sacks of cement. After circulating cement inside of 7 5/8" casing, close casing head to bradenhead cement between 7 5/8" casing and 10 3/4" casing.
- 8) Cut off casing 3' below ground and install permanent marker.

11200rammatic Well Skc
Denton North Wolfcamp Unit No. 6-26
Denton N. (Wolfcamp) Field
Lea County, New Mexico



5-17-78