

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.
---

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Polaris Production Corp.</b>	8. Farm or Lease Name <b>Priest</b>
3. Address of Operator <b>P. O. Box 1749, Midland, Texas 79701</b>	9. Well No. <b>7</b>
4. Location of Well UNIT LETTER <b>B</b> <b>330</b> FEET FROM THE <b>North</b> LINE AND <b>2310</b> FEET FROM THE <b>East</b> LINE, SECTION <b>1</b> TOWNSHIP <b>15-S</b> RANGE <b>37-E</b> N.M.P.M.	10. Field and Pool, or Wildcat <b>Denton Devonian</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3806 DF</b>	12. County <b>Lea</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPER. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon. Propose to set BP at 12,400 w/3 sx cement on top; cut 5½" csg. at free point; circulate mud-laden fluid; spot 100' cement plug at top of 5½" csg. stub; spot 100' cement plug across Abo Fm. (if exposed); spot 100' cement plug across Glorieta Fm. (if exposed); spot 100' cement plug at bottom of 8 5/8" intermediate; spot 100' cement plug opposite salt section; and spot 10 sx cement cap at top with 4" marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED  TITLE President DATE May 27, 1975

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: