

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATION	

5a. Indicate Type of Lease
State ☒ Fed ☐
5. State Oil & Gas Lease No.
B-9774

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator ARCO Oil & Gas Company, Division of Atlantic Richfield Company	8. Farm or Lease Name State "T"
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240	9. Well No. 4
4. Location of Well UNIT LETTER M 660 FEET FROM THE South LINE AND 660 FEET FROM West LINE, SECTION 2 TOWNSHIP 15S RANGE 37E NMPM.	10. Field and Pool, or Whdcat Denton Devonian
15. Elevation (Show whether DF, RT, GR, etc.) 3813' DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	COMMENCE DRILLING OPNS. ☐
PULL OR ALTER CASING ☐	CASING TEST AND CEMENT JOBS ☐
OTHER ☐	OTHER ☐
PLUG AND ABANDON ☒	ALTERING CASING ☐
CHANGE PLANS ☐	PLUG AND ABANDONMENT ☐


17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug & abandon. This zone is depleted & no other zones exist to be economical to produce.

1. Rig up, kill well, install BOP & POH w/comp assy.
2. RIH w/cmt retr, set retr @ 11,850'.
3. Squeeze cmt perms 11,900-54' w/75 sx 55 Pozmix cmt w/ 6% Halad-9, dump 50' on top of retr. Spot heavy mud between plug.
4. Perf 7" csg @ + 8320'. Circ cmt behind 7" csg w/approx 1300 sx 50/50 Pozmix w/.6% Halad-9, 1/4# flocelex sk to + 2000'. Run temp survey.
5. Spot 100' cmt plug + 4500' inside 7" OD csg.
6. Spot 100' cmt plug + 2150' inside 7" OD csg.
7. Spot 10 sx cmt plug @ surface. Cut off well head 3' below GL, install regulation dry hole marker. Clean & level location for abandonment.

THE COMMISSION MUST BE NOTIFIED 24 HOURS BEFORE THE DEEDING OF PLUGGING & ABANDONMENT FOR THE CLOSURE TO BE APPROVED

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED 	TITLE Dist. Drlg. Supt.	DATE 5-9-80
Orig. Signed By Jerry Sexton		
APPROVED BY 	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		

MAY 19 1980