

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
		5. State Oil & Gas Lease No. E-2433
1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name -
2. Name of Operator Shell Oil Company (Western Division)		8. Farm or Lease Name State A
3. Address of Operator P.O. Box 1509, Midland, Texas 79701		9. Well No. 1
4. Location of Well UNIT LETTER L 1980 FEET FROM THE south LINE AND 660 FEET FROM THE west LINE, SECTION 2 TOWNSHIP 15S RANGE 37E N.M.P.M.		10. Field and Pool, or Wildcat Denton-Devonian
15. Elevation (Show whether DF, RT, GR, etc.) 3820' DF		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Proposed Operation: Drill out bridge plugs at 12,365' & clean out to 12,469'.

1. Pull 2" tubing, packer & Kobe pump.
2. Drill out Model "N" CIBP's at 12,365', clean out to 12,469'.
3. Rerun production equipment and place on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed By

N. W. Harrison

N. W. Harrison

TITLE **Senior Exploitation Engineer**

DATE **February 23, 1966**

SIGNED

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: