

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
310 Old Santa Fe Trail, Room 206  
Santa Fe, New Mexico 87503

WELL API NO. 30-025-05246
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-8944
7. Lease Name or Unit Agreement Name MEXICO "F"
8. Well No. 1
9. Pool name or Wildcat DENTON DEVONIAN

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Crestridge Drilling and Production Company, LLC	
3. Address of Operator P.O. Box 1114	
4. Well Location Unit Letter C : 660 Feet From The North Line and 1980 Feet From The West Line Section 2 Township 15S Range 37E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3814 DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
- (1) Notify Oil Conservation Division 24 Hours prior to commencing operations (Approx. 11-30-01)
  - (2) Rig Up well service unit and pull out of hole 2 7/8" Tubing.
  - (3) Run in hole with retrievable bridge plug and packer to 12,050 Ft. set and test casing to 500 PSI.
  - (4) Pull out of hole with retrievable bridge plug and packer, run back in hole with permanent bridge plug and set at 12,050 Ft.
  - (5) Test Casing to 500 PSI for 30 minutes with no more than 50 PSI bleedoff.
  - (6) Circulate wellbore and pull out and lay down 2 7/8" tubing.
  - (7) Submit to Oil Conservation Division report of temporary abandonment.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE R.A. McBride Jr. TITLE Manager DATE 10-26-01

TYPE OR PRINT NAME R.A. (Rick) McBride Jr. TELEPHONE NO. 915-685-7071

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: