

OF COPIES RECEIVED		
DISTRIBUTION		
SANITARY		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-55

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>B-8944</b>	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name -----
2. Name of Operator <b>Skelly Oil Company</b>		8. Farm or Lease Name <b>Mexico "F"</b>
3. Address of Operator <b>P. O. Box 1351, Midland, Texas 79701</b>		9. Well No. <b>3</b>
4. Location of Well UNIT LETTER <b>E</b> <b>1980</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>West</b> LINE, SECTION <b>2</b> TOWNSHIP <b>15S</b> RANGE <b>37E</b> N.M.P.M.		10. Field and Pool, or Wildcat <b>Denton Devonian</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3816' DF</b>		12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
OTHER <b>Visqueeze Devonian perfs. 12062-12083' <input checked="" type="checkbox"/></b> <b>and Test Devonian perfs. 12497-12512'</b>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Move in workover rig. Pull rods and tubing.
- 2) Test Devonian perfs. 12497-12512'.
- 3) If test of Devonian perfs. 12497-12512' indicates non-commercial pay, set cast iron bridge plug at 12497'.
- 4) Visqueeze Devonian perfs. 12062-12083' to eliminate excessive water production.
- 5) Return well to production status pumping Devonian perfs. 12062-12083' and also, perfs. 12497-12512', if commercial.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED **(Signed) D. R. Crow** **D. R. Crow** TITLE **Lead Clerk** DATE **9-9-74**

APPROVED BY **Joe D. Lamey** TITLE **Dist. I, Supv.** DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: