

COPIES RECEIVED		
TRIBUTION		
FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
5. State Oil & Gas Lease No. B-8944	
SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name - - - - -
2. Name of Operator Skelly Oil Company	8. Farm or Lease Name Mexico "F"
3. Address of Operator P. O. Box 1351, Midland, Texas 79701	9. Well No. 8
4. Location of Well UNIT LETTER <u>D</u> <u>967</u> FEET FROM THE <u>North</u> LINE AND <u>990</u> FEET FROM THE <u>West</u> LINE, SECTION <u>2</u> TOWNSHIP <u>15S</u> RANGE <u>37E</u> NMPM.	10. Field and Pool, or Wildcat Denton Wolfcamp
11. Elevation (Show whether DF, RT, GR, etc.) 3816' DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
		OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Moved in pulling unit 1-18-74.
- Set 5-1/2" cast iron bridge plug at 9060' and capped with 4 sacks of cement to 9030'.
- Shot off 5-1/2" OD casing at 4745' and salvaged 4777', overall measurement.
- Spotted 100 sacks of regular cement across 5-1/2" casing stub 4595'-5062'.
- Spotted 50 sacks of regular cement 1850-2090'.
- Cut off 9-5/8" OD casing at 618' and salvaged 620', overall measurement.
- Spotted 70 sacks regular cement plug across 9-5/8" OD casing stub 558-668'.
- Spotted 70 sacks regular cement plug across bottom of 13-3/8" OD casing 272-372'.
- Spotted 10 sacks regular cement plug from surface to 20'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED (Signature) D. R. Crow TITLE Lead Clerk DATE 1-31-74

APPROVED BY (Signature) TITLE OIL & GAS INSPECTOR DATE
 CONDITIONS OF APPROVAL, IF ANY: