

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
<b>B-8944</b>	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
<b>Skelly Oil Company</b>		<b>Mexico "F"</b>
3. Address of Operator		9. Well No.
<b>P. O. Box 1351, Midland, Texas 79701</b>		<b>12</b>
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER <b>A</b> , <b>660</b> FEET FROM THE <b>East</b> LINE AND <b>660</b> FEET FROM		<b>Denton Wolfcamp</b>
THE <b>North</b> LINE, SECTION <b>2</b> TOWNSHIP <b>15S</b> RANGE <b>37E</b> NMPM.		
15. Elevation (Show whether DF, RT, CR, etc.)		12. County
<b>3812' DF</b>		<b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Moved in casing pulling unit 8-24-73.
- Set 5-1/2" cast iron bridge plug at 9100' and capped with cement to 9075'.
- Shot off and recovered 5-1/2" OD casing at 5392'.
- Spotted 50 sack cement plug 5380-5480', 50 sack plug 4700-4800', 50 sack plug 2200-2300', and 10 sack plug from surface to 30'.
- Installed dry hole marker.

The 13-3/8" OD 48# casing, set at 324', 8-5/8" OD 32# casing, set at 4752' were left in the hole. The unrecoverable portion of the 5-1/2" OD 17# casing from 5392-9253' was also left in the hole.

All intervals not cemented were filled with 10# mud.

Well plugged and abandoned 8-28-73.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED (Signed) D. R. Crow D. R. Crow TITLE Lead Clerk DATE August 30, 1973

APPROVED BY John W. Runyan TITLE Geologist DATE \_\_\_\_\_  
CONDITION OF APPROVAL, IF ANY: