

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Atlantic Richfield Company	8. Farm or Lease Name B.C. Dickinson "B"
3. Address of Operator P. O. Box 1978, Roswell, New Mexico 88201	9. Well No. 5
4. Location of Well UNIT LETTER <u>M</u> <u>330</u> FEET FROM THE <u>South</u> LINE AND <u>330</u> FEET FROM THE <u>West</u> LINE, SECTION <u>12</u> TOWNSHIP <u>15-S</u> RANGE <u>37-E</u> NMPM.	10. Field and Pool, or Wildcat Denton-Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.) 3793' DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

This well was shut in on 2/5/68 because of low, uneconomical production. We propose to P & A the well in the following manner:

Set 40 sk cement plug 9300-9125' (perfs 9220-9300')
Set 25 sk cement plug across top of 7" liner @ 4573'.
Set 20 sx cement in top of well

9#/gal salt gel mud will be left between all plugs. All casing strings will remain intact. Dry hole marker will be installed and location cleaned and levelled.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>D.C. Lutes</u>	TITLE <u>Dist. Prlg. Supervisor</u>	DATE <u>11-3-70</u>
APPROVED BY <u>John W. Runyan</u>	TITLE <u>Geologist</u>	DATE <u>11-3-70</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED
JAN 10 1970
OIL CONSERVATION COMM.
WASH. D.C.