

NO. OF COPIES RECEIVED		
DISTRIBUTION		
AMT. FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - "A" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Atlantic Richfield Company		8. Farm or Lease Name B. C. Dickinson "B"
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240		9. Well No. 4
4. Location of Well UNIT LETTER <u>E</u> <u>2310</u> FEET FROM THE <u>North</u> LINE AND <u>330</u> FEET FROM THE <u>West</u> LINE, SECTION <u>12</u> TOWNSHIP <u>15S</u> RANGE <u>37E</u> NMPM.		10. Field and Pool, or Wildcat Denton Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.) 3804' DF		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- On 1/16/76 rigged up & installed BOP. Set 7" CIBP @ 9240'. Filled hole w/heavy gelled mud. Dumped 6 sx C1 C cmt on top of CIBP @ 9240', top of cmt plug @ 9205' (35' plug).
- Spotted 100' C1 C cmt plug across top of 7" csg liner @ 4609', 50' below & 50' above top of liner. Top of plug @ 4555'.
- Ran free pt on 9-5/8" OD csg, free pt indicated @ 620'. Jet cut 9-5/8" csg @ 620'. Shot csg, no movement. WIH w/nitro can on WL & blew collar @ 610'. Pulled & rec 610' of 9-5/8" csg.
- Spotted 70 sx C1 C cmt across 9-5/8" csg stub @ 610' (100' plug), top of plug @ 560'.
- Spotted 80 sx C1 C cmt across 13-3/8" OD csg shoe @ 369' (100' plug) top of plug @ 319'.
- Spotted 10 sx C1 C cmt @ surf, installed regulation dry hole marker, cleaned & levelled location. P&A eff 1/24/76. Final Report.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>La Roy Kroett</u>	TITLE <u>Dist. Drlg. Supv.</u>	DATE <u>1/27/76</u>
APPROVED BY <u>John W. Runyan</u>	TITLE <u>Geologist</u>	DATE <u></u>
CONDITIONS OF APPROVAL, IF ANY:		