Submit 3 Copies To Appropriate Distr	rict		f New Me		~	Form C-103	
Office Energy, Minerals and Natural Resources					WELL API N	Revised March 25, 1999	
1625 N. French Dr., Hobbs, NM 88240					30-025- 05367 05370		
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION					5. Indicate T		
District III 1220 South St. Francis Dr.					STATI		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM					6. State Oil 777790	& Gas Lease No.	
87505 SUNDRY NOTICES AND REPORTS ON WELLS					7. Lease Nan STATE (ne or Unit Agreement Name:	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					SIAIL		
1. Type of Well: Oil Well X Gas Well Other							
2. Name of Operator					8. Well No.		
Apache Corporation					9. Pool name or Wildcat		
3. Address of Operator 6120 South Yale, Suite 1500 Tulsa, OK 74136-4224					LOVINGTON ABO		
4. Well Location							
Unit Letter O :1980	foot fr	om the SOUTH line :	and 660 feet	from the EAST lin	ne		
Unit Letter O .1980	r rect ii				NMPM	County LEA	
Section 31		Township 10. Elevation (Sho	16S Ki	ange 37E R RKR RT GR e		County LEM	
	4 * ·	3826 GR					
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data							
NOTICE OF INTENTION TO:					RSEGUENI	REPORT OF.	
PERFORM REMEDIAL WOR		PLUG AND ABAND	ON 🗆	REMEDIAL WO	RK	☐ ALTERING CASING ☐	
TEMPORARILY ABANDON		CHANGE PLANS		COMMENCE D	RILLING OPNS.	☐ PLUG AND X ABANDONMENT	
PULL OR ALTER CASING		MULTIPLE COMPLETION		CASING TEST	AND		
OTHER: .	· · ·			OTHER:			
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or							
starting any proposed wor	rk). SE	E RULE 1103. For I	Multiple Con	npletions: Attach	Wellbore diagrai	n or proposed completion of	
recompilation.				Aı	meand as to a	hanta Cd vvv u s	
2-21-02			20001	Li:	ppioved as to p shiliry under by	olugging of the Well Bore.	
7.00 A.M. Add Date of the American State of					rface restoratio	on is completed.	
6.20 D.M. SHITT DOV	VN						
6:30 P M. SPOT FIRS	6:30 P M SPOT FIRST PLUG CLASS h 156 50 SK @ 7790' ½ BPM 2800 PSI						
6:20 P.M. 6:30 P.M. SPOT FIRST PLUG CLASS h 156 50 SK @ 7790' ½ BPM 2800 PSI 6:40 P.M. SHUT DOWN PULL UP TO 6100' 7:30 P.M. SPOT 2 ND PLUG 30 SK CMT ½ BPM 2800 PSI CLASS C CEMENT 7:40 P.M. SHUT DOWN PULL UP TO 4700' 8:30 P.M. SPOT 3 RD PLUG 30 SK CMT ½ BPM 2800 PSI CLASS C CEMENT							
7:30 P.M. SPOT 2. PLUG 30 SK CM1 ½ BFM 2800 FSI CLASS C CEMENT 7:40 P.M. SHUT DOWN PULL UP TO 4700'							
7:40 P.M. SHUT DOWN PULL UP TO 4700 8:30 P.M. SPOT 3 RD PLUG 30 SK CMT ½ BPM 2800 PSI CLASS C CEMENT							
Q:AOPM SHUTDUWN (1 all Y-CV) ==							
10:00 P.M. WASH UP	& SHU	JT DOWN UNTIL N	EXI DAY			E accinos &	
6:40 P.M. SHUT DOWN PULL UP TO 6100' 7:30 P.M. SPOT 2 ND PLUG 30 SK CMT ½ BPM 2800 PSI CLASS C CEMENT 7:40 P.M. SHUT DOWN PULL UP TO 4700' 8:30 P.M. SPOT 3 RD PLUG 30 SK CMT ½ BPM 2800 PSI CLASS C CEMENT 8:40 P.M. SHUT DOWN 10:00 P.M. WASH UP & SHUT DOWN UNTIL NEXT DAY CONTINUED ON NEXT PAGE							
I hereby certify that the information above is true and complete to the best of my knowledge and belief.							
SIGNATURE augh touch TITLE Production Tech DATE IT 5 02							
Type or print name Total Fager JAN 1 7 2003							
(This space for State use)	سايد	J. Wink					
APPPROVED BY CARY WANK TITLE DATE Conditions of approval of any: Conditions of approval of approval of any: Conditions of a							
Conditions of approval, it any: Conditions of approval, it and the conditions of approval, it are conditions of approval, and the condition approval, and the conditions of approval, and the condition ap							
						•	

2-22-02 COMPUTALOG PERF @ 3125' 4 HOLES 10:30 A.M. START F/W SPACER START SMT (50 SK) ½ BPM 2800 PSI 2%CACL 16:34 A.M. 10:50 A.M. SHUT DOWN WASH UP TO PIT SHUT DOWN & PULL COIL TUBING UP TO 2700' 1 :14 A.M. START DISPLACEMENT TO SQEEZE 5 BBLS 11:16 A.M. 11:25 A.M. SHUT DOWN/WAIT ON CEMENT FOR 3 HRS 2:30 P.M. TAG PLUG @2825' TOP 3:30 P.M. SET PLUG @ 2228' 25 SK 3:40 P.M. START DISPLACEMENT 10.5 BBLS SHUT DOWN 4:00 P.M. WAIT TO PERF - SET SURFACE PLUG & SQ @ 285' 4:15 P.M. SET 35 SK PLUG & 2% CACL 7:00 P.M. SHUT DOWN WAIT ON CMT 2% CACL 7:30 P.M. 10:00 P.M. TOP OUT & 10 SK & WAIT CMT FALLING BACK STILL - WAIT UNTIL 2-23-02 & TOP OUT 2-23-02 TOP OUT 5 SK. 8:00 A.M.

WELL PLUGGED AS PER BILL PRIDE-OCD.

