NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shaped as a present of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

		Indicate Nature of Report by Cl	necking Belo	₩	
REPORT ON BEGINNING DRILLING OPERATIONS	X	REPORT ON RESULT OF T	EST	REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL		REPORT ON RECOMPLETI OPERATION	ON	REPORT ON (Other)	
		March 11	1052	Midland, Texas	
		March 11,	±722	(Place)
Following is a report on the	work done	and the results obtained under th	e heading no	oted above at the	
The Texas Company (Company or Operator)			Mamie Graham		
McVay & Stafford I	or Operator) Pillin	g Company Well No	, 1	in the	ec. 31 ,
(COB	tractor)				
			Pool,	Lea	County.
The Dates of this work were as fold	sws: Se	e below			•••••
Notice of intention to do the work	(wa	not) submitted on Form C-102 o	n	(Cross out incorrect words)	, 19,
and approval of the proposed plan		•			
D	ETAILED	ACCOUNT OF WORK DONE	ND RESUI	TS OBTAINED	
		TD: 326-Red Bed	ls		
Spudded 11:00 P.M.	3-5-53				
Ran & cemented 10 ; Cement circulated.	jts 309 Compl	of 13-3/8" casin eted 5:30 P.M. 3-6	g at 32 -53.	24' with 350 sacks.	·
	cement	at 5:30 P.M. 3-7-	53. Tested	ested cement job by i okay.	
Commenced drilling pressure method be:	iore ar	O ST CAT ATTTTTE			
Commenced drilling pressure method be:	rore an	d at cer diffine.			
Commenced drilling pressure method be:	iore ar	d at car diffing.			
Commenced drilling pressure method be:	iore ar	d al cal dilling.			
Commenced drilling pressure method be:	iore ar	d al cal dilling.			
pressure method be:					
pressure method be:	iore ar	(Compan	y)	(Title)	
Witnessed by	Vame)	(Compan	y)		and complete
Pressure method be:	Vame)	(Compan	y)	(Title)	and complete
Witnessed by	Vame)	(Compan I here to the Name Position	by certify the best of the control on Asst	(Title)	and complete

(x,y) = (x,y) + (x,y

tack wing the