## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

40. 07 COPIES SECEIVES	
HOLTUBIRTEID	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

DISTRICT SUPERVISOR

CONDITIONS OF APPROVAL, IF ANY:

## OIL CONSERVATION DIVISION

DISTRIBUTION	P.O. DOY and	Fa C 102
SANTA FE	P. O. BOX 2088	Form C-103 Revised 10-1-7
FILE	SANTA FE, NEW MEXICO 87501	
U.S.O.S.	1	5a. Indicate Type of Lease
LAND OFFICE		State X Fee
OPERATOR	4	
DEPATOR	J	5. State Oil & Gas Lease No.
		B-7897
SUNDR	Y NOTICES AND REPORTS ON WELLS	
USE "APPLICAT	POSALS TO DRILL OR TO DEEPEH OR PLUG BACK TO A DIFFERENT RESERVO! ION FOR PERMIT —"" (FORM C-101) FOR SUCH PROPOSALS.)	·· (
1.		7. Unit Agreement Name
OIL X GAS WELL	ATU. 4	
2. Name of Operator	OTHER.	
		8. Farm or Lease Name
Texaco Producing Inc.		State "P"
3. Address of Operator		9. Well No.
DO Day 720 Habbs Nov	Mayica 00240	2
PO Box 728, Hobbs, Nev	V MEXICO 88240	10. Field and Pool, or Wildcat
	200	
UNIT LETTER	1980 FEET FROM THE SOUTH LINE AND 380	Lovington Paddock
THE West LINE, SECTION	on 32 township 16S range 37E	
	TOWNSHIP RANGE J/L	—— "MPM: \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3783' GR	
čimminimi.	777774	Lea (\\\\\\\
Check A	Appropriate Box To Indicate Nature of Notice, Repo	ort or Other Data
NOTICE OF IN	TENTION TO	SEQUENT REPORT OF:
•		regoriti itel oitt of .
FREDRIM REMEDIAL WORK		<u>(A)</u>
THE CAME WE MEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JO	• 🔲
	OTHER	
OTHER		
17, Describe Proposed or Completed Ope	erations (Clearly state all pertinent details, and give pertinent dates,	including estimated date of starting any proposed
work) SEE RULE 1103.		
1) MIRU 1/5/88. Ins	stall BOP. Set CIBP at 8300'. Cap with 40	O' cement. New
PBTD: 8260'.	, out 1 2011 200 2121 at 2000 1 24p 11.101.	
	25001 Donf Daddock with All cacing gun w	i+h 2 19DI + 6167  72
	-3500'. Perf Paddock with 4" casing gun w	
/8, 85, 89, 9/, 6	5200', 06, 16, 21, 26, 31, 36, 39, 44, 49,	52, 57, 85, 89, 6300,
08, 16, 20 (24 in	ntervals, 48 holes).	
<ol><li>TIH with packer</li></ol>	to 6006'. Acidize perfs with 15000 gallor	ns gelled 15% NE-FE and
15000# 20/40 sand	d and 25 ball sealers.	
	quipment. Start pumping.	
	tial test ending 8:00 AM, 1/26/88. Pump 30	O RO 146 RW 20 MCF
666 GOR, Gravity	, 21 60 2+ 600	0. DO 3 1 10 DIT 20 1101. 3
ooo don, dravits	7 31.0 ac oo	
	·	
•	•	
		•
	•	•
-		
		· · · · · · · · · · · · · · · · · · ·
as, a nereby certify that the information a	above is true and complete to the best of my knowledge and belief.	39/-35/1
1/	· ·	•
DIENCO Ha Hear		endent <sub>BATE</sub> 2/24/88
	/ Hobbs Area Superinto	PNUPIU
	Hobbs Area Superinte	ENGENT DATE 2/24/00
ORIGINAL SKINE	D BY JERRY SEXTON	ENGENT DATE Z/24/00

...FEB 29 1988

ARCENTIES OFFICE