

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy Minerals and Natural Resources Department

Form O-10
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer 00, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Alamogordo, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No. **B7897**

7. Lease Name or Unit Agreement Name
STATE "P"

8. Well No. **5**

9. Pool name or Wildcat
LOVINGTON

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☐ OTHER ☐ **PLUGGED & ABANDONED**

2. Name of Operator
Greenhill Petroleum Corporation (Getty oil Co)

3. Address of Operator
11490 WESTHEIMER, STE., 200, HOUSTON, TX 77077

4. Well Location
Unit Letter **M** : **330** Feet From The **SOUTH** Line and **330** Feet From The **WEST** Line
Section **32** Township **16S** Range **37E** NMPM **LEA** County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: **DRILL OUT AND REPLUG PER NMOC R 9431** ☒

SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) MIRU AND CLEANOUT CSG. TO $\pm 2043'$. TEST CSG. TO 500#. DRILL OUT AND CLEANOUT TO $\pm 3115'$. DRILL INTO CMT. 50' AND POOH. DRILL OUT CMT. AND CLEAN CSG. TO $\pm 6065'$.
- 2) MIRU CEMENT EQUIPMENT.
- 3) PU TBG. AND TIH TO 4650'. SPOT 20 SX CMT. PLUG. PULL OUT SLOWLY AND POOH TO $\pm 3200'$. WOC 4 HRS. POOH TO $\pm 3420'$.
- 4) SPOT 45 SX CMT. PLUG IN CSG/OPEN HOLE. POOH TO $\pm 2095'$. WOC 4 HRS.
- 5) POOH TO $\pm 2140'$. SPOT 40 SX CMT PLG IN OPEN HOLE 8 5/8" CSG. PULL OUT OF CMT. SLOWLY * POOH. WOC 4 HRS. POOH TO $\pm 60'$.
- 6) SPOT 10 SX SURFACE PLUG.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Michael J. Newport TITLE Land Manager-Permian Basin DATE 5-8-91

TYPE OR PRINT NAME Michael J. Newport TELEPHONE NO. 955-1146

(This space for State Use)

APPROVED BY DAVID L. SEXTON TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

THE COMMISSION MUST BE NOTIFIED
OF ANY CHANGES TO COMPLETION WORK

MAY 14 1991