

COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p>SUNDRY NOTICES AND REPORTS ON WELLS</p> <p>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>5a. Indicate Type of Lease</p> <p>State <input type="checkbox"/> Fee <input checked="" type="checkbox"/></p> <p>5. State Oil & Gas Lease No.</p>
<p>1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P&A</p> <p>2. Name of Operator Atlantic Richfield Company</p> <p>3. Address of Operator P. O. Box 1978, Roswell, New Mexico 86201</p> <p>4. Location of Well</p> <p>UNIT LETTER I 2086 FEET FROM THE South 706 FEET FROM THE East LINE, SECTION 15 TOWNSHIP 15-S RANGE 38-E NMPM.</p> <p>15. Elevation (Show whether DF, RT, GR, etc.) 3742' DF</p>		<p>7. Unit Agreement Name</p> <p>8. Farm or Lease Name Corbin</p> <p>9. Well No. 1</p> <p>10. Field and Pool, or Wildcat Medicine Rock-Dev.</p> <p>12. County Lea</p>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

<p>PERFORM REMEDIAL WORK <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>	<p>PLUG AND ABANDON <input type="checkbox"/></p> <p>CHANGE PLANS <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>	<p>REMEDIAL WORK <input type="checkbox"/></p> <p>COMMENCE DRILLING OPNS. <input type="checkbox"/></p> <p>CASING TEST AND CEMENT JOB <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>	<p>ALTERING CASING <input type="checkbox"/></p> <p>PLUG AND ABANDONMENT <input checked="" type="checkbox"/></p>
--	---	--	---

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well has been plugged & abandoned as follows:

Spotted 15 sk cement plug on top of DR plug from 12707-12565'. Shot off & pulled 360 jts of 5-1/2" casing (11488.63'). Spotted 35 sk common cement plug half in & half out of 5-1/2" csg stub @ 11500'. Set 35 sk cement plug from 8260-8160; 25 sk plug from 6455-6380; 35 sk plug from 4950-4850. Shot off 9-5/8" casing @ 900', unable to pull; shot @ 810', unable to work pipe free; shot @ 693' RKB. Pld 24 jts 9-5/8" csg (679.64'). Spotted 45 sk cement plug half in & half out of 9-5/8" csg stub @ 693'. Spotted 10 sk cement plug from 30' to 15' RKB. Set dry hole marker. Well P & A 2/2/69.

We will notify you by letter when location is ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>O. D. Bretches</u>	TITLE <u>Dist. Dlg. Supervisor</u>	DATE <u>2-10-69.</u>
APPROVED BY <u>John W. Runyan</u>	TITLE <u></u>	DATE <u>JUN 5 1970</u>
CONDITION OF APPROVAL, IF ANY:		