

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name	
Clara M. Roberts	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
Medicine Rock (Dev.)	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator	3. Address of Operator	4. Location of Well
	Polaris Production Corp.	P. O. Box 1749, Midland, Texas 79702	UNIT LETTER <u>E</u> <u>330</u> FEET FROM THE <u>West</u> LINE AND <u>1980</u> FEET FROM THE <u>North</u> LINE, SECTION <u>23</u> TOWNSHIP <u>15-S</u> RANGE <u>38-E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)			
3728.5 GL			

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1108.

The following work is proposed to begin on 12-21-88 @ 8:00 a.m. New Mexico time (48 hrs. notice will be given before actual operations begin).

1. Set Model "D" Packer w/ bridging bar & ²~~25~~ sx cmt @ 12,745'.
2. Set CIBP w/ 2 sx cmt @ 12,585'.
3. Load hole w/ 9.5# mud.
4. Shoot & recover 7500' of 5½" csg.
5. Set plugs as follows:
 - 25 sx @ 8170-7966'
 - 25 sx @ 7550-7450'
 - 40 sx @ 6450-6350'
 - 40 sx @ 4900-4800'
 - 40 sx @ 1480-1380'
 - 10 sx & marker @ surface

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE President DATE 11-1-88

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE 11-1-88
CONDITIONS OF APPROVAL, IF ANY: