

COPIES RECEIVED		
DISTRIBUTION		
FE		
S.S.		
AD OFFICE		
ERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>E-437</b>	
7. Unit Agreement Name	
8. Farm or Lease Name <b>Tekell</b>	
9. Well No. <b>2-4</b>	
10. Field and Pool, or Wildcat <b>Denton Devonian South</b>	
12. County <b>Lea</b>	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER- <input type="checkbox"/>
Name of Operator <b>Signal Oil &amp; Gas Co.</b>		
Address <b>125 Central Bldg., Midland, Texas 79701</b>		
Location of Well UNIT LETTER <b>A</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>East</b> LINE, SECTION <b>5</b> TOWNSHIP <b>-16-8</b> RANGE <b>-38-E</b> NMPM.		

15. Elevation (Show whether DF, RT, GR, etc.)

**3755 GR**

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Load Hole w/Brine Water & Gel
2. Set Cast-Iron Bridge Plug @ 12700' w/2EksCement on to of Plug (Perforations @ 12910')
3. Set 100' Cement Plug in & out of 7" Casing Stub @ approx. 7000'
4. Set 25 Sx. Cement Plug above Glorieta @ approx. 6000'
5. Set 25 Sx. Cement Plug in 9 5/8" Casing Shoe @ 4995'
6. Set 100' Cement Plug in & out of 9 5/8" Casing Stub @ approx. 1500'
7. Set 25 Sx. Cement Plug in 13 3/8" Casing Shoe @ 314'
8. Cement Plug 10' to Surface in 13 3/8" Casing & Weld Plate & Marker

TD of Well **13,200'**

Plugging & abandonment operations to begin approx. January 7, 1969

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <b>George Van Housen</b>	TITLE <b>Agent</b>	DATE <b>Jan. 3, 1969</b>
APPROVED BY <b>[Signature]</b>	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		