STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

בווטו אוויין בוואר אוויין אוני		TIVILLE
NO. OF COMICE ACCEIVED		
DISTRIBUTION		
SANTA FE		
FILE	Ī	
U.S.G.S.	İ	
LAND OFFICE	1	
OPERATOR	1	

CIL CONSERVATION DIVISION

DISTRIBUTION	P. O. 80 X 2088	Form C-103	
SANTA FE	SANTA FE, NEW MEXICO 87501	Revised 10-1-7	
FILE		5a. Indicate Type of Lease	
U.S.G.S.			
LAND OFFICE		State Fee X	
OPERATOR		5. State Oil & Gas Lease No.	
SLI	NORY MOTICES AND DEPORTS ON WELLS	MATTHER THE STATE OF THE STATE	
(00 NOT USE THIS FORM FO	NDRY NOTICES AND REPORTS ON WELLS IN PROPOSALS TO DISILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. CICATION FOR PERMIT - 11 (FORM C-101) FOR SUCH PROPOSALS.		
031 8770	CICATION FOR PERMIT TO (FORM C-101) FOR SUCH PROPOSALS.)	7, Unit Agreement Name	
01L 6A9		7. Only Agreement Name	
were were	other Dry Hole		
vame of Operator	8, Farm or Lease Name		
Nucorp Energy, Inc.		Mona Wilson	
Address of Operator		9. Well No.	
/a Odl Panarta & Ca	on Countries. Two Day 762 Williams 00040	•	
ecation of Well	as Services, Inc., Box 763, Hobbs, NM 88240	10. Field and Pool, or Wridgat	
	·		
UNIT LETTER M	990 FEET FROM THE South LINE AND 660 FEET FROM	Wildcat	
		Milling the second	
West	SECTION 21 TOWNSHIP 165 RANGE 38E		
CINC, S	TOWNSHIP RANGE JUL _ GUPM		
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County	
	3723 GR	Lea	
Che	ck Appropriate Box To Indicate Nature of Notice, Report of Otl	her Data	
	ck Appropriate Box To Indicate Nature of Notice, Report of Otl		
		her Data FREPORT OF:	
NOTICE O	F INTENTION TO: SUBSEQUENT	FREPORT OF:	
NOTICE O	FINTENTION TO: SUBSEQUENT	T REPORT OF:	
NOTICE O	FINTENTION TO: PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPHS.	T REPORT OF:	
NOTICE O	FINTENTION TO: SUBSEQUENT	T REPORT OF:	
NOTICE O	FINTENTION TO: PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPHS.	FLUG AND ABANDONMENT	
NOTICE O	FINTENTION TO: PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPHS. CHANGE PLANS CASING TEST AND CEMENT JQB	FLUG AND ABANDONMENT	

Plug and abandon 7/17/80 as follows:

Set CIBP @ 4900 & cap with 35' cement Cut 4 1/2" casing at 3800' and pulled Ran tubing & loaded hole with mud Spot plug 3759-3859 with 14 sacks Class C cement Tag top of plug at 3734 Spot plug 2930-3030 with 22 sacks Class C cement Spot plug 2068-2168 with 22 sacks Class C cement Spot 10 sack plug at surface with marker Cleaned location

16. I nereby certify that the information shove is true and complete to the best of my knowledge and belief.					
AIGNED JL 4227/1 // 1/65	TITLE	Agent	DATE 7/22/80		
800			range		
PPROVED BY	YITLE 3	<u>a de la companya de</u>	QATE		