

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-025-07279
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name: Mai-Tai
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	8. Well No. 1	
2. Name of Operator Manzano Oil Corporation	9. Pool name or Wildcat Wildcat	
3. Address of Operator P.O. Box 2107, Roswell, NM 88202-2107		
4. Well Location Unit Letter <u>A</u> : <u>660</u> feet from the <u>North</u> line and <u>660</u> feet from the <u>East</u> line Section <u>22</u> Township <u>16S</u> Range <u>38E</u> NMPM Lea County		
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3709' GL		

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☒ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

7/25/00 Pick up 12-1/4" bit and one 7" drill collar. Drill 20' surface plug. TIH. Tag @ 290'. Drill & ream to 528'.
7/26/00 Wash to 498'. Wash and ream to 947'. POOH. LD 12-1/4" bit. Pick up 8-3/4" bit. Drill to 965'. POOH.
7/27/00 Pick up 6-1/8" bit. Try to find 9-5/8" csg. No luck. POOH.
7/28/00 Pick up 11-3/4" x 6' slip jt. TIH w/slip jt. Drill from 959' to 965'. Stop making progress. POOH. Had red bed core inside slip jt.
7/29/00 Pick up 12-1/4" bit. TIH. Drill to 997'. Did not hit anything. Circled clean. POOH.
8/01/00 Pump 65 sks Class C + 4% CaCl from 340'. POOH. Wait one hr. TIH. Tag @ 240'. Set 10 sks surface plug. P&A well.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dennis Broach TITLE VP Engineering DATE 8/01/00

Type or print name

Telephone No.

(This space for State use)

APPROVED BY Billy E. Brubaker TITLE

DATE

Conditions of approval, if any:

JAN 31 2001

