DISTRIBUTION SANTA FE		
SANTA FE		Form C-103 Supersedes Old
	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103
FILE	THE MENTES STE CONSERVATION COMMISSION	Effective 1-1-65
U.S.G.S.	1366	5a. Indicate Type of Lease
LAND OFFICE	1.55 (1.17) A 199	State Fee X
OPERATOR	1.50	5. State Oil & Gas Lease No.
		5. State Off & Gds Ledse No.
SLINIC	DEN MOTICES AND DEPORTS OF MELL	- homenman
(DO NOT USE THIS FORM FOR P	DRY NOTICES AND REPORTS ON WELLS ROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. ATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)	
1.	(FORM C-TUT) FOR SUCH PROPOSALS.)	
OIL GAS WELL	OTHER-	7. Unit Agreement Name
2. Name of Operator	oract.	
Amerada Hess Corpo	ration	8, Farm or Lease Name
3. Address of Operator		S. B. Rose
P. O. Box 1920 - H	ohba Novi Maridaa	9. Well No.
4. Location of Well	obus, New Mexico	1
7 1000		10. Field and Pool, or Wilccat
UNIT LETTER,	1980 FEET FROM THE North LINE AND 1980 FEET F	NOM Undesignated Abo
THE West LINE, SECTION 35 TOWNSHIP 16-S RANGE 38-E NAME		» (
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3705' DF	Lea
Check	Appropriate Box To Indicate Nature of Notice, Report or	Other Data
NOTICE OF I	NTENTION TO: SUBSEQUE	ENT REPORT OF:
		THE ON TOP.
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING GARAGE
FEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	ALTERING CASING
PULL OR ALTER CASING	CHANG- PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
	OTHER_	_
OTHER		
work) SEE RULE 1103.	perations (Clearly state all pertinent details, and give pertinent dates, includ	ing estimated date of starting any proposed
from 4733' to 4847'	ment in 5-1/2" casing from 6200' to 6488'. Sh 44 joints. Spotted 35 sacks cement in and out	4 6 7 1 - 4
C	Shot 8-5/8" csg. at 760'. Recovered 18 join out of 13-3/8" casing from 238' to 305'. Spo asing from 0' to 13'. Installed 4" x 5' dry head effective 8-20-69.	nts. Spotted 50
plugged and abandon	asing from 0' to 13'. Installed 4" x 5' dry he ed effective 8-20-69.	nts. Spotted 50 tted 10 sacks cement: ole marker. Well
plugged and abandon	asing from 0' to 13'. Installed 4" x 5' dry hed effective 8-20-69.	nts. Spotted 50 tted 10 sacks cement: ole marker. Well
plugged and abandon	asing from 0' to 13'. Installed 4" x 5' dry he ed effective 8-20-69. above is true and complete to the best of my knowledge and belief.	nts. Spotted 50 tted 10 sacks cement: ole marker. Well
plugged and abandon	asing from 0' to 13'. Installed 4" x 5' dry he ed effective 8-20-69.	nts. Spotted 50 tted 10 sacks cement: ole marker. Well
plugged and abandon	asing from 0' to 13'. Installed 4" x 5' dry he ed effective 8-20-69. above is true and complete to the best of my knowledge and belief. TITLE District Superintendent SUPERV SOR DISTRICT	nts. Spotted 50 tted 10 sacks cement: ole marker. Well