JUPLICATE.

W MEXICO OIL CONSERVATION MMISSIONE

MISCELLANEOUS REPORTS ON WELLS R

Submit this report in triplicate to the Oil Conservation Commission District Office when the Completed is completed. It should be signed and filed as a report on beginning drilling operations well to test of casing shut off, result of plugging of well, and other important operations, even though the work was thought an

Indicate natur	e of report by checking bel	ow.	
REPORT ON BEGINNING DRILLING OPERATIONS	REPORT ON	REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		PULLING OR OTHERWISE	;
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	X		
	4=17=52 Date	Hobbs, New M	
ollowing is a report on the work done and the results of Phillips Chemical Company Company or Operator	Chem State	Well No.	in th
NE/4 NR/4 of Sec. 4	, т 15 S	, R. 32E	, N. M. P. M
Unnamed Pool	Lea		County
d approval of the proposed plan was not) obtaine DETAILED ACCOUNT OF V Well drilled to total depth of 1	ed. (Cross out incorrect word WORK DONE AND RESUI	s.) .TS OBTAINED ak with cement to 990	o61.
ad approval of the proposed plan we kwas not) obtained DETAILED ACCOUNT OF V	ed. (Cross out incorrect word WORK DONE AND RESUL 10,000', plugged bac casing set at 9903 gular followed by 10 2872'. Opened ports 10 sacks returns.	s.) At with cement to 990 B. Cemented in 2 st Comented in 2 st	061. tages: lar. r at
Well drilled to total depth of 1 Ran 317 joints, 9893', 5-1/2" OD 1st stage - 300 sacks % gel reg Pumped plug to float collar at 9 7555'. Circulated 3-1/2 hours, gel regular cement. Pumped plug with 1000# for 30 minutes before	ed. (Cross out incorrect word WORK DONE AND RESUL 10,000', plugged bac casing set at 9903 gular followed by 10 2872'. Opened ports 10 sacks returns.	c.ts obtained c.ts o	o6!. tages: lar. r at cs 8% ing
Well drilled to total depth of 1 Ran 317 joints, 9893', 5-1/2" OD 1st stage - 300 sacks 8% gel reg Pumped plug to float collar at 9 7555'. Circulated 3-1/2 hours, gel regular cement. Pumped plug with 1000# for 30 minutes before	ed. (Cross out incorrect word WORK DONE AND RESUR 10,000', plugged bac D casing set at 9903 gular followed by 10 9872'. Opened ports 10 sacks returns. It to stage collar at a and after drilling Company	ck with cement to 990 3'. Cemented in 2 st 30 sacks 4% gel regular 5 in Model "F" collar 2nd stage - 600 sack 4. 7555'. Tested cast 5 plug.	061. tages: lar. r at cs 8% ing